

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 21 Sep 2021

Preliminary Advice

Vehicle No	: SLN8751Y	Accident Date	: 16/09/2021
Make	: HONDA CIVIC	Policy No.	: MPC21P00182900
Assignment Date	: 20/09/2021	Excess	: S\$0.00
Date of Inspection	: 21/09/2021	Est. Duration of Repair	: 12
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,955.10
Revised Amount	:S\$	8,737.70
Check Items (Estimated)	:S\$	2,513.20
Total	:S\$	11,250.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	48,914.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,086.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.