

NOT Allowed

Excess ?
21/9/21

21/9/21

12 days. John H. Baker party.

Date : 18.09.2021

Chassis : MRHFC1660HT00007

OD Ins. ECICS Ltd 1/5 \$9200

ECICS Ltd 1/5 \$7200

ESTIMATE

[illegible]

38	1	RR BOOTLID WEATHERSTRIP	17	\$ 46.00	X
39	1	RR BOOTLID STOPED	17	\$ 6.00	X
40	1	RR BOOTLID STOPED LOW	17	\$ 13.00	X
41	1	RR BOOTLID DRAIN PLUG	17	\$ 4.00	X
42	1	RR DOOR INNER TRIM BOARD LH	17	\$ 671.00	X
43	1	RR FENDER INNER TRIM LH	26	\$ 52.00	/
44	1	RR BOOTLID LOGO	17	\$ 13.00	X
45	1	RR BOOTLID VTEC TURBO EMBLEM	17	\$ 26.00	X
46	1	RR BOOTLID CIVIC EMBLEM	17	\$ 13.00	X
47	1	RR FUEL FILLER CAUTION STICKER	261	\$ 8.00	✓
48	1	RR DOOR BLACK STICKER LH(frt)	261	\$ 26.00	✓
49	1	RR DOOR BLACK STICKER LH(rr)	261	\$ 26.00	✓
50	1	RR DOOR OUTER MLDG LH	17	\$ 52.00	X
51	1	RR DOOR OUTER UPP MLDG LH	17	\$ 65.00	X
52	1	RR FENDER INNERSHIELD LH	700	\$ 59.00	✓
53	1	LH ROCKER PANEL GARNISH LH	17	\$ 117.00	X
54	1	FRT GRILLE BASE	500	\$ 91.00	/
55	1	FRT GRILLE LOGO	17	\$ 20.00	X
56	1	FRT GRILLE CHROME MLDG	17	\$ 98.00	X
57	1	FRT GRILLE CHROME MLDG RH	500	\$ 78.00	X
58	1	FRT GRILLE TOP SEAL	17	\$ 26.00	X
59	1	FRT BUMPER	261	\$ 299.00	/
60	1	FRT BUMPER RETAINER RH	261	\$ 12.00	/
61	1	FRT BUMPER BRACKET RH	500	\$ 26.00	/
62	1	FRT BUMPER TOP CENTRE RETAINER	17	\$ 143.00	X
63	1	FRT BUMPER REINFORCEMENT	DD	\$ 299.00	X
64	1	FRT BUMPER FOG LAMP COVER RH	500	\$ 20.00	/
65	1	FRT BUMPER LOW CENTRE GRILLE	17	\$ 72.00	X
66	1	RR BUMPER	261	\$ 338.00	✓
67	1	RR BUMPER LOW	17	\$ 39.00	X
68	1	RR BUMPER SIDE RETAINER LH	261	\$ 16.00	/
69	1	RR BUMPER BRACKET LH	261	\$ 7.00	/
70	1	RR BUMPER GARNISH LH	500	\$ 13.00	/
71	1	RR BUMPER REFLECTOR LH	17	\$ 11.00	X
72	1	RR BUMPER FINISHER LH	261	\$ 13.00	✓
73	1	RR BUMPER REINFORCEMENT	17	\$ 156.00	X
74	1	FRT HEADLAMP RH	261	\$ 1,014.00	/
75	1	FRT SIGNAL LAMP RH	261	\$ 33.00	/
76	1	FRT FOG LAMP RH	261	\$ 208.00	✓
77	1	RR TAILLAMP LH	500	\$ 221.00	✓
78	1	RR BOOTLID LAMP LH	17	\$ 98.00	X
79	1	FRT WIPER WASHER TANK	17	\$ 33.00	X
80	1	FRT WIPER WASHER PUMP	17	\$ 39.00	X
81	1	FRT WIPER WASHER TANK NECK	17	\$ 16.00	X
82	1	FRT WHEEL BEARING RH	17	\$ 98.00	X
83	1	FRT WHEEL BEARING HUB RH	17	\$ 124.00	X
84	1	FRT KNUCKLE RH	17	\$ 163.00	X
85	1	FRT LOW ARM RH	17	\$ 208.00	X

86	1	FRT LOW ARM BALLJOINT RH	17	\$ 59.00	X
87	1	FRT STABILIZER LINK RH	17	\$ 46.00	X
88	1	FRT ABS SENSOR RH	17	\$ 85.00	X
89	1	FRT SHOCK ABSORBER RH	17	\$ 260.00	X
90	1	FRT SHOCK ABSORBER TOP MOUNTING RH	17	\$ 39.00	X
91	1	FRT TIE ROD RH	17	\$ 46.00	X
92	1	FRT STEERING RACK END RH	17	\$ 39.00	X
93	1	RR WHEEL BEARING LH	Damaged	\$ 176.00	✓
94	1	RR KNUCKLE LH	Bad	\$ 169.00	✓
95	1	RR LOW ARM 1 LH	Bad	\$ 72.00	✓
96	1	RR LOW ARM 2 LH	Bad	\$ 52.00	✓
97	1	RR UPP ARM LH	Bad	\$ 169.00	✓
98	1	RR TRAILING ARM LH	Bad	\$ 72.00	✓
99	1	RR STABILIZER LINK LH	17	\$ 39.00	X
100	1	RR ABS SENSOR LH	17	\$ 65.00	X
101	1	RR SHOCK ABSORBER LH	17	\$ 182.00	✓
102	1	RR SHOCK ABSORBER TOP MOUNTING LH	17	\$ 104.00	X

\$ 14,341.00 6302
 Cost +10% \$ 1,434.10
 \$ 15,775.10

Special Nett

1	10	FRT BUMPER CLIP	17	\$ 50.00	30
2	10	FRT GRILLE CLIP	17	\$ 50.00	X
3	6	FRT SUPORT GARNISH CLIP	17	\$ 30.00	X
4	10	FRT FENDER INNERSHIELD CLIP	17	\$ 50.00	30
5	1	FRT RIM RH	17	\$ 500.00	X
6	1	FRT TYRE RH	17	\$ 300.00	X
7	1	RR RIM LH	17	\$ 500.00	X
8	1	RR TYRE LH	500	\$ 300.00	X
9	10	RR BUMPER CLIP	17	\$ 50.00	30
10	10	RR FENDER INNERSHIELD CLIP	17	\$ 50.00	X
11	6	RR FENDER INNER TRIM CLIP	17	\$ 30.00	X
12	6	RR END PANEL TOP GARNISH CLIP	17	\$ 30.00	X
13	6	RR BOOTLID INSULATOR CLIP	17	\$ 30.00	X
14	1	RR WINDSCREEN SEALANT	17	\$ 60.00	40
15	1	RR WINDSCREEN SOLAR FILM	17	\$ 200.00	X
16	1	RR QUARTER GLASS SEALANT	17	\$ 60.00	30
17	1	RR QUARTER GLASS SOLAR FILM	17	\$ 100.00	X

FRT Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00	500
Carry out spray painting on affected area, FRT BONNET, FRT BUMPER, FRT FENDER RH, FRT DOOR RH <i>Suppl</i>	\$ 1,000.00	600
To conduct anti rust of under carriage tuff coat	\$ 11 80.00	X
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	20
To remove and replace RHF under carriage parts	\$ 11 300.00	X
To conduct 4 wheel alignment	\$ 120.00	80
To conduct reset of engine light on	\$ 11 300.00	X
To refocus headlamp <i>Asph</i>	\$ 80.00	X

RR Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,600.00	1200
Carry out spray painting on affected area, RR BOOTLID, RR BUMPER, RR END PANEL, RR FENDER LH, RR DOOR LH, LH ROCKER PANEL	\$ 1,600.00	1000
To conduct anti rust of under carriage tuff coat	\$ 11 80.00	X
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	20
Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 300.00	80
To remove and refix reverse sensor and conduct test	\$ 80.00	40
To remove and refix reverse camera and conduct test	\$ 11 80.00	X
To conduct transfer of parts from old bootlid to new bootlid	\$ 11 120.00	X
To conduct water leakage test after repairs of vehicle	\$ 11 30.00	X
To apply door sealant to door	\$ 60.00	✓
Remove and replace LHR under carriage parts	\$ 300.00	150
To remove and refit fuel tank to facilitate accident repair	\$ 200.00	60
To remove and refit rear windscreen due to replacement of rear fender	\$ 180.00	120
To remove and refix rear quarter glass	\$ 120.00	60

Total \$ 25,955.10

GST 7% \$ 1,816.86

Grand Total \$ 27,771.96

P-6694
102
P-7363-40
S.N-160
L

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: