

# Vin's

## Estimated Cost of Repair

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

Attention To : China Taiping Insurance  
(Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

Case Ref. No. : TP/092021/4999  
Date : 24-09-2021  
Accident Date : 17-09-2021

### Vehicle Details

Make & Model : Jaguar XE 2.0 I4D TSS  
Chassis No : SAJAB4AN1GA933427  
Registration No : SML8096D

### Third Party Vehicle Details

Registration No : PC6341X

S/N	Description	Qty	Amount (S\$)
1	FRONT LH HEADLAMP	1.00	cuq ✓ \$3,667.30
2	FRONT BUMPER	1.00	de ✓ \$2,180.00
3	FRONT BUMPER LH SIDE RETAINER	1.00	de ✓ \$68.00
4	FRONT LH FENDER	1.00	Ry ✓ \$920.00
5	FRONT LH FENDER INNER SHIELD	1.00	an x \$410.20
6	FRONT LH FENDER INNER SHIELD CLIPS @ \$2.70	10.00	an x \$27.00
7	FRONT LH WHEEL SPORT RIM	1.00	wt ✓ \$2,271.40
8	FRONT LH WHEEL SHOCK ABSORBER	1.00	x an \$693.10
9	FRONT LH WHEEL KNUCKLE ARM	1.00	? \$2,048.90
10	FRONT LH WHEEL KNUCKLE ARM BEARING	1.00	? \$815.60
11	FRONT LH WHEEL LOWER ARM	1.00	x \$739.20
			\$13,840.70
Discount -10%			(\$1,384.07)
			\$12,456.63
12	FRONT LH WHEEL TYRE	1.00	x an \$280.00
13	TO CHECK WHEEL ALIGNMENT	1.00	80 \$120.00
14	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	1.00	150? \$280.00 ✓
15	TO DIAGNOSE ELECTRICAL COMPONENTS	1.00	50 \$180.00
16	TO REPAIR DAMAGES	1.00	500 \$680.00
17	TO SPRAY PAINTING	1.00	500 \$780.00

3277.62

1254

bt -

bt -

9576.12  
8618.50

1280

Subtotal w/o GST: \$14,776.63

8618.50

1280

9898.50

45879.00

\* 4 days

Tanpin 97415749  
wp 24/9/21 @ 1315 04 days  
tanpin @ kuantan  
L/S Resurvey after repair

Issued by Raymond Teo

This is a computer-generated document. No signature is required.