

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009805/EES3Q2
Date: 29/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKU329L	Insured Vehicle No :	SLP920T
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU329L		
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 (A)	Engine No:	CAXF19249
Reg. Date:	29/06/2015 (Man. Year: 2014)	Chassis No:	WVWZZZ16ZFM002354
Colour:	White	Odometer:	84186 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,501.91	1,857.49	1,644.42	46.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,181.91	3,977.49	5,204.42	56.68
+ GST 7.00/7.00% (S\$)	642.73	278.42	364.31	56.68

Nett Amount (S\$)	9,824.64	4,255.91	5,568.73	56.68
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,584.36		

INSPECTION

Date of Assignment: 20/09/2021

Date Inspected: 21/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2021)
Parts:	143	VOLKSWAGEN JETTA GP 1.4 TSI 90 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU329L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Dented	1,355.34 FS	*1,355.34 FS
2	1		*SPOILER	Cut	502.15 FS	*502.15 FS
3	1		*BUMPER REINFORCEMENT	Not Necessary	650.77 FS	*- FS
4	1		*FOAM INSERT	Not Necessary	143.61 FS	*- FS
5	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	84.92 FS	*- FS
6	1		*GUIDE PIECE LHS BUMPER BRACKET (UPPER)	Not Necessary	91.28 FS	*- FS
7	1		*GUIDE PIECE RHS BUMPER BRACKET (UPPER)	Not Necessary	91.28 FS	*- FS
8	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	91.28 FS	*- FS
9	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	91.28 FS	*- FS
10	1		*REVERSE SENSOR	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**3,501.91****1,857.49**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	2,520.00	840.00
2	SPRAY PAINT	New	2,400.00	800.00
3	B&P CHECK SHORT CIRCUIT/ HARNESS REPAIR	New	280.00	0.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >