

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Steve (LKK)
21/9/21, 10.30am

Wk P/P
Bel Sy
3 days

Quotation
Non binding - Preview

Page 1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
TAN
KWANG YEW
31 PHENG GECK AVENUE
#05-06 SENNETT RESIDENCE
Singapore 321105

Document no.
Document date 17-09-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021035549/ 1
Job order date 17-09-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKU329L	1634G5	29-06-2015	WVWZZZ16ZFM002354	JETTA TSI High 90 D7F	59,243

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5C6807421H GRU	Cover For Bumper Primed	1	pcs.	1,355.34	#1	1,355.34	1,450.21
5C6807433J	Spoiler	1	pcs.	502.15	#1	502.15	537.30
5C6807305	Bumper	1	pcs.	650.77	#1	650.77	696.32
	REINFORCEMENT						
5C6807251F	Foam Insert	1	pcs.	143.61	#1	143.61	153.66
5C6807863B	Attachment Strip	1	pcs.	84.92	#1	84.92	90.86
	BUMPER CTR BRACKET						
5C6807393E	Guide Piece	1	pcs.	91.28	#1	91.28	97.67
	LHS BUMPER BRACKET (UPPER)						
5C6807394E	Guide Piece	1	pcs.	91.28	#1	91.28	97.67
	RHS BUMPER BRACKET (UPPER)						
5C6807375	Guide Piece	1	pcs.	91.28	#1	91.28	97.67
	LHR BUMPER BRACKET (SIDE)						
5C6807376	Guide Piece	1	pcs.	91.28	#1	91.28	97.67
	RHR BUMPER BRACKET (SIDE)						
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	3	pcs.	800.00	#1	2,400.00	2,568.00
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	INDIA DIRECT SETTLEMENT						
	DOA: 17/09/2021						
	TP VEH: SMA9037B						
	SURVEY BY:						

Quotation valid till 24-09-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,421.91	7%	642.73	9,181.91	9,824.64
Total	760.00	8,421.91		642.73	9,181.91	9,824.64

Customer

Service Advisor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VOLKSWAGEN CENTRE SINGAPORE
Alexandra Road
Singapore 159934
Z. Reg. No.: 199101494Z
ST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page 2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Mr
TAN
KWANG YEW
31 PHENG GECK AVENUE
#05-06 SENNETT RESIDENCE
Singapore 321105

Document no.
Document date 17-09-2021
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 30001
Job order number 2021035549/ 1
Job order date 17-09-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SKU329L	1634G5	29-06-2015	WVWZZZ16ZFM002354	JETTA TSI High 90 D7F	59,243

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.