

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Sep-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6156 J

1 pc	Boot lid	\$	1,119.00 ✓DT
1 pc	Boot lid lock	\$	99.00 ?
1 pc	Bootlid lock cable	\$	35.00 ?
1 pc	Bootlid striker	\$	21.00 ?
1 pc	Bootlid emblem	\$	27.00 ✓nec
1 pc	Bootlid CRDi	\$	29.00 ✓nec
1 pc	Boot lid rubber weatherstrip	\$	96.00 ✓nec
1 pc	Boot lid lower garnish	\$	290.00 ✓Det
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 ✓shf
1 pc	Bootlid inner trim	\$	190.00 ?
2 pcs	Bootlid rear license plate lamps @ \$30.00	\$	60.00 ?
1 pc	End panel inner garnish	\$	74.00 ?
1 pc	End panel	\$	250.00 ^
1 pc	Spare tyre clamp	\$	8.00 ?
1 pc	Rear bumper	\$	696.00 ✓Cut
1 pc	Rear bumper lower cover	\$	206.00 ✓Cut
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 ✓nec
1 pc	Rear bumper inner sponge	\$	114.00 ?
1 pc	Rear bumper reinforcement	\$	607.00 ?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 ?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 ?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 ?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 ✓Scr
2 pcs	Rear n/s air vent @ \$30.00	\$	60.00 XSVc
2 pcs	Rear n/s & o/s tail lamps	\$	842.00 ✓cra
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	\$	700.00 ✓cra
2 pcs	n/s & o/s tail lamp panel @ \$215.00	\$	430.00 Xr
1 pc	Floorboard panel	\$	625.00 Xr
1 pc	Floorboard panel trim	\$	205.00 ?
1 pc	Exhaust pipe	\$	1,009.00 Xr
1 pc	Exhaust pipe hanger	\$	28.00 XSVc
1 pc	Rear o/s fender	\$	1,205.00 ✓Det
1 pc	Rear o/s fender top chrome moulding	\$	97.00 XSVc/sh.
1 pc	Rear o/s fender inner shield	\$	120.00 ?

1 pc Rear windscreen
1 pc Rear windscreen moulding

\$ 801.00 ^{/scr}
\$ 87.00 ^{X SUC}
\$ 10,592.00
\$ 1,059.20
\$ 9,532.80

Less 10%

S/NETT

1 set Rear bumper clips
1 set End panel inner garnish clips
1 set Bootlid inner trim clips
1 set Bootlid lower garnish clips
1 set Bootlid stickers
1 set Reverse sensor
1 pc Rear bumper top protector
1 pc Rear o/s fender sticker
1 set Floorboard compartment insulating paddings
1 set o/s door stickers
1 set Sealant
1 pc Rear number plate with casing

\$ 48.00 ^{/nec}
\$ 30.00 ^{/nec}
\$ 52.00 ^{/nec}
\$ 60.00 ^{/nec}
\$ 100.00 ^{/nec}
\$ 280.00 ^{200 Cert}
\$ 80.00 ^{/nec}
\$ 60.00 ^{/nec}
\$ 120.00 [?]
\$ 100.00 ^{/nec SO}
\$ 50.00 ³⁰
\$ 50.00 ^{/nec BT}

Sundry
To dismantle / refit rear exhaust pipe

\$ 50.00 ^{X SUC}
\$ 120.00 ⁴⁰

To dismantle / refit rear new windscreen glass and moulding

\$ 120.00 [✓]

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 ⁴⁰

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 ⁶⁰

To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut end panel, floorboard compartment, rear o/s fender, rear n/s & o/s tail lamp panels. Including knock-out, straighten, repair, reshape and adjust of the same, etc

900
\$ 2,400.00

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment, rear o/s fender, rear n/s & o/s tail lamp panels, rear o/s door

900
\$ 1,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is subject to final approval from insurance company
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

To apply rustproofing on the repaired and replaced panels.

\$ 250.00 ⁵⁰
\$ 15,602.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer

Signature:

Date:

Theruan@lkkauto.com
82235769
6clays w/p
21/9/21 1445
L/S after repair photos