

# AUTO BULLOX PTE.LTD

53 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park S(408934)

Business Reg No: 201919765N

Tel: 6841 5383 / Fax: 6841 6043

E-Mail: autobullox@gmail.com

To: Motor Claims Department

Date: 17/09/2021

Vehicle No: SKR7398G

Model: Toyota Corolla Altis

## Estimated Repair Cost For SKR7398G (Toyota Corolla Altis)

QTY	Parts	Amount
1	Bootlid panel	\$ 986.40 Xr
1	Bootlid weatherstrip	\$ 295.50 XSvc
1	Bootlid inner lock	159 \$ 286.20 /jam
2	Bootlid hinge @ SGD 78.00	\$ 156.00 /shf
1	Bootlid logo	\$ 94.20 /nec
1	Bootlid emblem "Corolla"	45-bos 67.50 /nec
1	Bootlid emblem "Altis"	41 \$ 72.40 /nec
1	Bootlid outer garnish	\$ 295.60 XSvc
1	Bootlid inner trim garnish	\$ 286.70 XSvc
1set	Bootlid inner trim garnish clips	\$ 48.00 XNN
1	Bootlid lamp o/s	328 \$ 545.70 /Cra
1	Rear windscreen glass moulding	\$ 195.40 XNN
1	Taillamp o/s	3 \$ 786.50 /Cra
1	Taillamp panel o/s	\$ 214.50 Xr
1	Rear bumper	5819 \$ 925.50 /Cut
1	Rear bumper side retainer @ SGD 68.50	\$ 137.00 /nec
1	Rear bumper bracket @ SGD 64.20	96 \$ 128.40 /nec
1	Rear bumper reinforcement	\$ 320.80 Xr
1	Rear bumper sponge	\$ 115.60 XSvc
1	Rear bumper reflector o/s	58 \$ 196.40 /Cra
1	Rear fender o/s	\$ 1,086.70 Xr
1	Rear fender inner shield o/s	\$ 297.40 XSvc
1set	Rear fender inner shield clips	1100 \$ 48.00 /nec
1	Rear fender inner trim garnish o/s	\$ 386.70 XSvc
1set	Rear fender inner trim garnish clips	\$ 55.00 XSvc
1	Rear fender air-vent garnish o/s	\$ 128.60 XSvc
1	End panel top garnish	\$ 286.40 XSvc
1set	End panel top garnish clips	\$ 38.00 XSvc
1	End panel	\$ 678.50 Xr
1	Rear exhaust box	\$ 955.20 XSvc
2	Rear exhaust mounting @ SGD 68.00	\$ 136.00 XSvc
1	Rear exhaust muffler	\$ 158.00 Xr

Parts Sum: \$ 10,408.80

Parts Less 25% : \$ 2,549.65

Parts Total: \$ 7,648.95

### Special Nett Items

1set	Rear Number Plate W/Garnish	\$	55.00	XSVU
1set	Reverse Sensor	\$	280.00	200 Gt
1	Rear windscreen primer & cleaner	\$	100.00	XNN
1	Rear windscreen sealant	\$	80.00	XNN
1	Rear windscreen inner seal	\$	60.00	XNN
1	Rear Windscreen sealant	\$	60.00	XNN

Special Nett Items Total: \$ 635.00

### Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Rear Damaged Areas (\$300.00 per day)	\$ 1,800.00 600
To Putty, Prep & Re-spray on affected Rear Damaged Areas (\$300.00 per panel) (Rear bumper, bootlid, end panel, rear fenders, spare tyre panel)	\$ 1,800.00 800
To Remove & Transfer Rear Bootlid Components, to Facilitate Repairs	NN X \$ 150.00 40
To Remove & Refit Rear Interior Floor Components to Facilitate Repairs	\$ 150.00 40
To Remove & Install Rear Windscreen Glass to Facilitate Repairs	\$ 150.00 XNN
To Remove & Install Rear Exhaust Pipe to Facilitate Repairs	NN X \$ 150.00 30
To Measure, Drill Holes on Replaced Rear Bumper, To Re-position & Install Reverse Sensor	\$ 150.00 40
To Conduct Water Seepage Test	\$ 120.00 30
To Disconnect Rear Wire Harness Electrical Components to Facilitate Repairs	\$ 120.00 30
To Apply Undercoating on the Affected Damaged Areas	\$ 280.00 30

Labour Charges Total: \$ 4,870.00

Parts Total: \$ 7,648.95

Special Nett Items Total: \$ 635.00

Labour Charges Total: \$ 4,870.00

Total Cost Of Repair: \$ 13,153.95

(Non-Inclusive of GST)

Thuvan@Lkhauto.com  
82235769  
4 days wp  
L/S after repair photos  
21/9/21 1300

F: 2700  
with  
hamankoh

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey
- To display
- Parts
- Third
- No
- Supplementary
- is subject

Acknowledged by Repairer

Signature:

Date: