

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009815/VGA3Q2**Date:** 30/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070151668
Claimant Vehicle No :	SHB4029L	Insured Vehicle No :	GBJ9790S
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	1418972843SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4029L		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B86432
Reg. Date:	09/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU503077993
Colour:	Blue	Odometer:	360430 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,533.65	3,085.30	448.35	12.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	1,310.00	230.00	14.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,073.65	4,395.30	678.35	13.37
+ GST 7.00/7.00% (S\$)	355.16	307.67	47.49	13.37
Nett Amount (S\$)	5,428.81	4,702.97	725.84	13.37
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$126.47/day) (S\$)		505.88		
(S\$)		5,408.85		
Liabe Amount (50.00%) (S\$)		2,704.43		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,706.43		
Global Sum Settlement (S\$)		2,700.00		

INSPECTION

Date of Assignment:	20/09/2021	
Date Inspected:	20/09/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	499.90 FL	*499.90 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	55.80 FL	*- FL
4	1		*REAR BUMPER UNDER SIDE COVER RH	Cut	232.00 FL	*148.40 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Necessary	112.70 FL	*112.70 FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	318.80 FL	*- FL
7	1		*REAR BUMPER ARM SUB-ASSY RH	Repair	139.60 FL	*- FL
8	1		*REAR BUMPER LOWER COVER	Cut	552.60 FL	*552.60 FL
9	1		*TAIL LAMP RH UPPER	Cracked	557.90 FL	*557.90 FL
10	1		*TAIL LAMP RH LOWER	Cracked	548.40 FL	*548.40 FL
11	1		*GARNISH SUB-ASSY BACK DOOR GARNISH	Cut	889.70 FL	*889.70 FL
12	1		*REAR BUMPER TOWING COVER	Cut	82.70 FL	*82.70 FL
13	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
14	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
15	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
16	1		*REAR TRUNK LID COMFORT & TEL NO,STICKER	Necessary	60.00 FS	*60.00 FS
17	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
18	1		*REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
19	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
20	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
21	1		*ORNAMENT SUB ASSY BACK DOOR	Cut	52.90 FL	*52.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,578.20	3,980.40
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,044.55	895.10
Total Parts (\$\$)					3,533.65	3,085.30
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	WIRING CHARGE	New	80.00	30.00
4	TOWING FEE	New	60.00	60.00
5	TUFF KOTE	New	50.00	20.00
Gross Labour Cost (\$)			1,540.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >