

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref	:31	05487615	Via Fax		Email.	
Date	:	20.09-21	Your Insured		GBJ 9790S	
Time of Fax	1	-	Date of Acc	:_	18-09.21	_
Attn: Motor Cla	aims Depai	rtment AlG				

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH. B

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle;
- Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Ms. Loke Wei Yieng (yy) Tel: 62148355 or HP: 86285336 lokewy@sparkcarcare.co Tel: 6214 8315 or HP: 9635 5305 Jumani Bin Masudin ♦ Lim Tien Siong Tel: 6214 8398 or HP: 9635 8546 Fax no. 65468156 ♦ Chiang Liat Choon Tel: 6214 8314 or HP: 9296 6006

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHB4029L

Make Model : Toyota : Prius Date: 20.09.2021

Insurance: AIG

MVA: MS. LOKE YY

Qty Parts Descrip	tion / Labour T	ype	Unit Price	Amount
1 REAR BUMPER				\$499.90
10 REAR BUMPER CLIPS				\$22.00
1 REAR BUMPER SIDE BRACKET RH				\$55.80
1 REAR BUMPER UNDER SIDE COVER RH				\$232.00
1 REAR BUMPER SIDE RETAINER	RH			\$112.70
1 REAR BUMPER REINFORCEME	NT			\$318.80
REAR BUMPER ARM SUB- ASS	YRH			\$139.60
1 REAR BUMPER LOWER COVER	:			\$552.60
1 TAIL LAMP RH UPPER				\$557.90
1 TAIL LAMP RH LOWER				\$548.40
1 GARNISH SUB-ASSY BACK DOO	OR GARNISH			\$889.70
1 REAR BUMPER TOWING COVE	₹			\$82.70
1 REAR TRUNK LIG LOGO (Prius)	1			\$60.80
1 REAR TRUNK LIG LOGO (Hybrid				\$52.40
	SUB TOTAL			\$4,125.30
	LESS 25%			\$1,031.33
	DISCOUNTED TOTAL			\$3,093.98
REAR TRUNK LID APPS STICKE	P			\$40.00
REAR TRUNK LID COMFORT & 1				\$60.00
REAR BUMPER ADVERTISEMEN				\$50.00
REAR FENDER ADVERTISEMEN				\$100.00
REAR FENDER ADVERTISEMEN				\$100.00
REAR BUMPER RUBBER MAT	1 2000 KIT			\$50.00
INCAN BOWN EN NOBBEN WAT				\$150.00
				ψ130.00
Labour Charge PANEL BEATING			ľ	\$750.00
SPRAY PAINTING CHARGE				\$600.00
WIRING CHARGE				\$80.00
TOWING FEE				\$60.00
TUFF KOTE				\$50.00 \$50.00
TOFF KOTE	TOTAL LABOUR			\$1,540.00
	ESTIMATE TOTAL			\$4,783.98
	EOTHINA E TOTAL	- 1		Ψ+,1 00.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6363 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 20.09.2021 11:05

REGN NO. SHB4029L

Page: 1

Team:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4119952

JC NO305487615

MILEAGE

FUEL

JSTOMER

R/MS

COMFORT TRANSPORTATION PTE LTD

7010045

ISTOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755 L. (R)

(O)

(P)

SCOUNT CARD NO.

MAKE TOYOTA E.....F PRIUS HYBRID(G4)18.09.2021 23:50 TARGET DATE

Date

YR OF MANU. 09.01.2019

CHASSIS CODE JTDKB3FU503077993

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 18.09.2021

NATURE: 3P 18.09.2021 '


S/NO

of Service Advisor

returned to Service Reception upon collection

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:	The model and which the control of t
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
wledgement Slip	Exit Pass
e No.: SHB4029L YY	Vehicle No.: SHB4029L

Name of Service Advisor

To be kept by Security Guard

Signature/Date