

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC21009817/Bqf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	12/11/2021	
	ATTN: SERENE LI	M		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	WC 6588T	Veh. Inspected		GBJ 1717H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1145113-001	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		21/09/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA 150 5MT	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFAT35Y10K212834	Colour		WHITE	
	Odometer	112290 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	GREEN MAX		5 mm	
	L/H Front Tyre	195 R15	GREEN MAX		5 mm	
	R/H Rear Tyre	155 R12	YOKOHAMA		5 mm	
	L/H Rear Tyre	155 R12	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.		General Information				
	Accident Date	17/09/2021	Inspection Dat	е	21/09/2021	
	Survey held at	at REVOLUTION AUTOMOTIVE PTE LTD				
		8 KAKI BUKIT AVE 4, #01-49/50/51/52/53/54 PREMIER @ KB, SINGAPORE 415875				
5a.	Remarks					
Ja.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.					
	3)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		7 Worki	ng Days	