

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0761/2021/ZK
DATE : 15-Sep-21
WIP : 44547

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ESCUDERO IAN HERMAN GONZALES
ADDRESS : 180 JOO CHIAT TERRACE
#03-05
SINGAPORE 427326
TELEPHONE : HP +65 98738049
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100321097-08
VEHICLE NO : **SKH 2634 K**
MODEL CODE : AUDI Q3 2.0 TFSI QU
MODEL YEAR : 22/11/2012
ENGINE NO : CCZ 290440
CHASSIS NO : WAUZZZ8U0DR030817
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Sep-21
PLACE OF ACCIDENT : UPPER EAST COAST ROAD AND
BEDOK SOUTH AVE 1 TURN

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 2634 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$ 280.00	✓
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$ 480.00	✓
3	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT. REINSTALL ALL PARTS REMOVED	\$ 4,400.00 1000	500 (Not including repairs or replacement of end panel)
4	TO RESPRAY REAR BUMPER, REAR LID REAR END PANELLING AND SPARE WHEEL HOUSING	\$ 4,000.00 1100	1650
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,352.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 2634 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Del'd</i>	1	\$ 1,580.00	✓	1264
2	REAR BUMPER FIXING SET <i>Me n</i>	1	\$ 124.00	x	
3	REAR BUMPER SPOILER <i>Del'd</i>	1	\$ 475.00	✓	380
4	REAR BUMPER CARRIER ?	1	\$ 651.00	?	} nn
5	HEX BOLT ?	6	\$ 30.00	?	
6	REAR TAIL LIGHT FOAM PIFCE - LH / RH LOWER ?	2	\$ 172.00	?	
7	REAR PARKING AID SENSOR <i>Me n</i>	3	TBC	+	
8	REAR PARKING AID SENSOR SEAL <i>Me n</i>	4	\$ 6.00	+	
9	REAR BUMPPER TAIL LIGHT - LH / RH <i>LH can't d</i>	2	\$ 240.4 602.00 301.	✓	
10	REAR LID TAIL LIGHT - LH <i>At</i>	1	\$ 1068 1,335.00	✓	
11	ADHESIVE	1	\$ 14.88	19.00	✓
12	AUDI EMBLEM	1	\$ 110	138.00	✓
13	Q3 EMBLEM	1	\$ 79.04	99.00	✓
14	2.0T EMBLEM	1	\$ 79.04	99.00	✓
15	QUATTRO EMBLEM	1	\$ 79.04	99.00	✓
16	REAR LID RUBBER <i>Me n</i>	1	\$ 205.00	+	
17	REAR PANEL TRIM <i>Me n</i>	1	\$ 572.00	+	
18	REAR PANEL ?	1	\$ 311.00	?	} nn
19	REAR PANEL REINFORCEMENT ?	1	\$ 790.00	?	
20	REAR WHEEL ARCH COVER - LH / RH <i>Me n</i>	2	\$ 412.8 516.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 7,823.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 2634 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR BUMPER WIRING SET <i>the u</i>	1	\$	515.00 ?	} nn
22	ARCrylic SEALANT ?	1	\$	180.00 ?	
23	CRAVITY WAX ?	1	\$	140.00 ?	
24	STONE CHIP ?	1	\$	180.00 ?	
25	METAL FILLER POWDER ?	1	\$	280.00 ?	
26	SUNDRIES ?	1	\$	300.00 ?	
TOTAL SPARE PARTS		:	\$	9,418.00	
TOTAL LABOUR CHARGES		:	\$	9,352.00	
GRAND TOTAL		:	\$	18,770.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *20/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *see Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT