

TP 1st Cap.
Denise.

SKB8572Y 2011 July.
Mercedes Benz C180 1597cc
WDD20404S2A545942

Distorted

Front LH Door Wing Mirror 1201 -

Front LH Door Rep's 1754 +

Front LH Door Weatherstripe ^{MP} ~ 246 +

Front LH Fender Emblem. ^{Nec} 58 -

Front LH Wheel Rim. ^{MP} _{ru} 1200 (SN) +

1259

1138-1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel Beating

~~500~~ 200

Spray Painting.

~~900~~ 700

Wiring

~~50~~ 30 970

To transfer door fitting.

150 +

To spray tuff coat

~~150~~ 40

To perform wheel alignment.

150. x.

total: 2103.10

1/5: 1650.

03 Days.