

ASS. REC. BY:

Steve

CS/AGI21009834/Eqf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OP/TP/WS/TP RES/OD-RES/EVA/INV/INV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

C10011723/JM

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Sent

Consistent? : Yes or No

Est. Repair:

5 days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

SMP 5056T

Yr Regn:

27/9/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Alcan

C.B.

1797

Colour:

Brown

A/O:

Insured / Std / NI / N

Sp. Reading

139023

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

2WR 80090163

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / 3/Rim / STD A/Rim or

Tyre Size:

F:

1.95/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

U/Bal:

4

mm

U/Bal:

4

mm

D.O.A.

17/9/21

Survey held at

Car Pro

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooflap or

The V/O / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV-113K

Steve finalised LS \$5400, 5 days (Red \$7564.85, 58%)

Time/Time, File, Pass to:



: Prel. Report

29/09 Typist



: Final Report

Time/Time, File Return to:

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Insp (\$

: Weekend (\$

: S + RS, SI

: Finance

: Other

TOTAL

Time/Time, File Return to:

TP

Time/Time, File Return to:

5400

**Adjustment of Spare Parts Costs for Repairs SMP 5056T
TOYOTA NOAH**

Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / 00	680.00
2	2-1	rear bumper reflector lamp LH& RH (RH) ?	260.00
3	2	Rear bumper side retainer LH & RH / OR	145.00
4	1 set	Rear bumper fasteners / ne	38.00
5	1	Tailgate / 00	1295.00
6	1	Tailgate center chrome garnish ?	665.00
7	1 set	Tailgate center garnish fasteners ?	32.00
8	1	Tailgate lock acurator ?	395.80
9	1	Tailgate Toyota emblem ?	95.50
10	1	Tailgate aqua emblem X	65.50
11	1	Tailgate inner trim board ?	425.00
12	1 set	Tailgate inner trim clips ?	38.00
13	1	Tailgate weatherstrip / TN	295.00
14	1	Tailgate inner lock ?	355.00
18	2	tailgate absorber LH & RH X	550.00
	2	tailgate rubber stopper LH & RH X	110.00
19	1	Rear windscreen X	1010.00
20	1	Taillamp RH assy X	580.00
21	1 set	Taillamp assy fastners RH X	18.00
23	1	Rear end panel ?	590.00
24	1	Rear end panel top garnish / CRU	285.00
25	1 set	Rear end panel top garnish fasteners / nee	22.00
26	1	Rear spare tyre panel X	700.00
27	1	Rear spare tyre board / CRU	810.00
28	1	rear fender garnish RH ?	360.00
29	2-1	rear fender inner trim board LH & RH (RH) / OR	1600.00
31	2	rear fender inner shield LH & RH X	500.00
32	1	Exhaust muffler X	620.00
			12539.80
		Less 25%	3134.95
			9404.85
		Special nett item	
1		Rear number plate w casing X	60.00
1		Rear windscreen sealant / nee	60.00
1		Rear end panel sealant ?	60.00
1		spare tyre panel sealant ?	60.00
1		Reverse sensor / LUT	200.00
1		reverse camera X	350.00
1		Rear floor panel insulation pad X	150.00
		Total parts	940.00

Adjustment of Labour Costs for Repairs

Spraying of affected areas	800.00	600
Carry out body cavity preservation	120.00	30
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	800.00	600
Remove & refix rear windscreen	150.00	120
Check wiring	80.00	30
Remove/refix boot compartment fittings & attachments for	80.00	50
To straighten rear chassis member	250.00	X
Remove & refix reverse sensor	80.00	30
To remove & refix exhaust	100.00	X
Remove & refix tailgate components	80.00	50
Remove & reinstall rear boot upholstery & vaccum nner	80.00	50
Total labour	2620.00	

Steve (LKK)
21/9/11, 3.30pm

WNL AL
5 4 5
L/S
My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: