

Adjustment of Spare Parts Costs for Repairs SMP 5056T
TOYOTA NOAH

Item	Qty	Vehicle parts description	S
1	1	Rear bumper / DD	680.00 /
2	2 / 1	rear bumper reflector lamp LH& RH (RH) ? / BR	260.00 130 /
3	2	Rear bumper side retainer LH & RH / BR	145.00 /
4	1 set	Rear bumper fasteners / RR	38.00 30 /
5	1	Tailgate / DD	1295.00 /
6	1	Tailgate center chrome garnish ? X RR	665.00 X
7	1 set	Tailgate center garnish fasteners ? X RR	32.00 X
8	1	Tailgate lock acurator ? X RR	395.80 X
9	1	Tailgate Toyota emblem ? X RR	95.50 X
10	1	Tailgate aqua emblem X RR	65.50 X
11	1	Tailgate inner trim board ? / BR	425.00 /
12	1 set	Tailgate inner trim clips ? / RR	38.00 30 /
13	1	Tailgate weatherstrip / TN	295.00 /
14	1	Tailgate inner lock ? / BT	355.00 /
18	2	tailgate absorber LH & RH X RR	550.00 X
	2	tailgate rubber stopper LH & RH X RR	110.00 X
19	1	Rear windscreen X RR	1010.00 X
20	1	Taillamp RH assy X RR	580.00 X
21	1 set	Taillamp assy fastners RH X RR	18.00 X
23	1	Rear end panel ? / DD	590.00 /
24	1	Rear end panel top garnish / CRV	285.00 /
25	1 set	Rear end panel top garnish fasteners / RR	22.00 /
26	1	Rear spare tyre panel X RR	700.00 X
27	1	Rear spare tyre board / CRV	810.00 /
28	1	rear fender garnish RH ? / BR	360.00 /
29	2 / 1	rear fender inner trim board LH & RH (RH) / BR	1600.00 681 /
31	2	rear fender inner sheild LH & RH X RR	500.00 X
32	1	Exhaust muffler X RR	620.00 X
			12539.80
		Less 25%	3134.95
			<u>9404.85</u>

6133
-25%
4599.75 /

Special nett item			
1	Rear number plate w casing	X RR	60.00 X
1	Rear windscreen sealant / RR		60.00 40 /
1	Rear end panel sealant ? / RR		60.00 30 /
1	spare tyre panel sealant ? X RR		60.00 X
1	Reverse sensor / LUT		200.00 /
1	reverse camera X RR		350.00 X
1	Rear floor panel insulation pad X RR		150.00 X
	Total parts		<u><u>940.00</u></u>

270 /

Adjustment of Labour Costs for Repairs

Spraying of affected areas	800.00	600 700
Carry out body cavity preservation	120.00	30
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	800.00	600 800
Remove & refix rear windscreen	150.00	120
Check wiring	80.00	30
Remove/refix boot compartment fittings & attachments for	80.00	50
To straighten rear chassis member	250.00	X
Remove & refix reverse sensor	80.00	30
To remove & refix exhaust	100.00	X
Remove & refix tailgate components	80.00	50
Remove & reinstall rear boot upholstery & vaccum inner	80.00	50
Total labour	2620.00	1860 ✓

Steve (LKK)

21/9/21, 3.00pm

WML AL

5 dys

L/S

My AL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be agreed by you and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4599.75

N- 270

L- 1860

6729.75

L/S- 5383.80

= 5400