

REF: CS1/LAW21009837/Avc

Special Instruction:

From (Person): NOREEN of CENTONS RODYK Date/Time: 21.09.2021
Estimated Cost: _____ Bill to: CENTONS RODYK

LS : 41,800

Third Parties:

Claimant:

Surveyor:

Workshop: Twincar Automotive Pte Ltd

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: BJN 8800 Insured: YM 4716C

at Workshop m/s Twincar Automotive Pte Ltd

Tel:

of 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921

Policy No: _____ Claim No: CCL/nbmy/34184.1538

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/10/2015
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red S ____/____%; Original 10 days)

Date/Time: 22/10/21 Submit Final Fig LS \$16,800, 9 days (Red \$ 25,000 / 60 %; Original days)

[illegible]

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____