

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401569M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 430180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64756601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

EXCISE - ?

Estimate No. : b1 59557

Date Estimated : 21/09/2021

Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Yio Kang Leng
53 Saraca Road

Singapore 807395

6 days

- ACCOUNT - 115

United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SM72Z	WBA4V32060EA25540	19/09/2017	430iA-C	84532

DESCRIPTION

To replace front bumper, fender left and attachments.

VALUE

To painting front bumper and fender left.

To check electrical wiring system at the front section for proper function including adjustment of headlights.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To replace left or right headlight.

To carry out body cavity preservation.
(Per panel).

To replace tyre and wheel rim including balancing. (1x).

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

Sundries.

150.00

Total Labour 1: 6,496.00

DESCRIPTION

ALLOY RIM 8JX18 M STAR SPK400

FRT LH SIDE PANEL

FRT LH 2 SIDE PANEL BRACKET

RH SUPPORT FOG LAMP (M)

FRT BUMPER PANEL PRIMED (M/PDC)

LH HEADLIGHT LED TECHNOLOGY

QTY

PRIC

VALUE

1 1,171.20

1 706.15

1 35.30

1 42.30

1 1,313.15

1 2,685.95

1,171.20

706.15

35.30

42.30

1,313.15

2,685.95

Total Parts : 5,954.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 418180
Fax: 63449773

116, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59557
Date Estimated : 21/09/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SM72Z	WBA4V32060EA25540	19/09/2017	430iA-C	84532

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,496.00
Parts	:	5,954.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	871.50
Grand Total	:	13,321.55

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **