

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21009845/KVF3N2**Date:** 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700020716
Claimant Vehicle No :	SGZ2489R	Insured Vehicle No :	SLQ4369D
Date of Loss:	18/09/2021	Nature of Claim:	TP
		Claim No:	1177434747SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ2489R	Engine No:	G4FC7U213580
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHDU41BR7U255532
Reg. Date:	24/10/2007 (Man. Year: 2007)	Odometer:	147460 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,704.68	3,178.53	3,526.15	52.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,875.00	1,640.00	1,235.00	42.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,579.68	4,818.53	4,761.15	49.70
Approved Total (Overridden) (S\$)		3,850.00		
Nett Amount (S\$)	9,579.68	3,850.00	5,729.68	59.81

INSPECTION

Date of Assignment:	21/09/2021		
Date Inspected:	21/09/2021	Inspected At:	BLK 225 #07-579 ANG MO KIO AVE 1 SINGAPORE 560225 REPAIRER : MASSIVE TRADING & AUTO
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	868.40 FL	*851.00 FL
2	2		*REAR BOOT LID HINGE	Repair	210.20 FL	*- FL
3	1		*REAR BOOT LID INNER INSULATOR	Serviceable	285.60 FL	*- FL
4	1		*REAR BOOT LID INNER LOCK	Dented	169.20 FL	*169.20 FL
5	1		*REAR BOOT LID OUTER LOCK	Serviceable	155.30 FL	*- FL
6	1		*REAR BOOT LID EMBLEM LOGO	Necessary	45.00 FL	*45.00 FL
7	1		*REAR BOOT LID EMBLEM AVANTE	Necessary	38.00 FL	*38.00 FL
8	1		*REAR BOOT LID OUTER HANDLE	Necessary	39.20 FL	*39.20 FL
9	2		*REAR NO PLATE LAMP	Serviceable	73.40 FL	*- FL
10	2		*REAR BOOT LID REFLECTOR	Serviceable	510.20 FL	*- FL
11	2		*REAR TAIL-LAMP ASSY	N/s Cut/O/s Mtg Cracked	571.20 FL	*571.20 FL
12	2		*REAR TAIL-LAMP PANEL	Repair	510.20 FL	*- FL
13	1		*REAR END PANEL	Bent	527.40 FL	*485.10 FL
14	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	85.60 FL	*85.60 FL
15	1		*REAR FENDER INNER TRIM	O/s Cracked	810.40 FL	*267.00 FL
16	1		*REAR BUMPER	Bent	525.60 FL	*484.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Serviceable	110.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	282.80 FL	*282.80 FL
19	1		*REAR BUMPER SPONGE	Cracked	185.70 FL	*119.00 FL
20	1		*REAR SPARE TYRE PANEL	Repair	955.10 FL	*- FL
21	1		*REAR SPARE TYRE COVER BOARD	Deformed	142.50 FL	*142.50 FL
22	1		*SPARE TOOL SPONGE	Serviceable	118.20 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Repair	655.70 FL	*- FL
24	1		*REAR NO PLATE	Serviceable	45.00 FS	*- FS
25	1		*SET REAR REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
26	20		*CLIP	Necessary	40.00 FS	*40.00 FS
27	1		*REAR BOOT RUBBER (50%)	Dented/Distorted	119.76 FS	*74.85 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,279.66	3,894.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,574.98	715.92
Total Parts (\$\$)	6,704.68	3,178.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,CUTTING & WELDING	New	1,200.00	700.00
2	TO PUTTY & SPRAY PAINT ON REAR ACCIDENTAFFECTED PORTION	New	1,200.00	800.00
3	CHECK/RECONNECT WIRING	New	45.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	150.00	60.00
5	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	100.00	60.00
6	REMOVE/RENEW REAR EXHAUST SILENCER	New	180.00	0.00
			Gross Labour Cost (S\$)	2,875.00
				1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >