

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Chan Wai Seng
BLK 319A Anchorvale Drive
#11-76
Singapore 543319

Not withair
61 Sep @ 3850/hr
Return After Paint
5 days

Vehicle No : SGZ 2489 R
Make : Hyundai Avante
Year : 2009

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid <i>851</i>	<i>At</i> \$868.40	✓
2 pcs	Rear boot lid hinge	\$105.10 <i>in</i> \$210.20	X
1 pc	Rear boot lid inner insulator	<i>in</i> \$285.60	X
1 pc	Rear boot lid inner lock	<i>in</i> \$169.20	✓
1 pc	Rear boot lid outer lock	<i>in</i> \$155.30	X
1 pc	Rear boot lid emblem " Logo "	<i>in</i> \$45.00	✓
1 pc	Rear boot lid emblem " AVANTE "	<i>in</i> \$38.00	✓
1 pc	Rear boot lid outer handle	<i>in</i> \$39.20	✓
2 pcs	Rear no plate lamp	\$36.70 <i>in</i> \$73.40	X
2 pcs	Rear boot lid reflector	\$255.10 <i>in</i> \$510.20	X
2 pcs	Rear tail-lamp assy <i>all in</i>	\$285.60	✓
2 pcs	Rear tail-lamp panel	\$255.10 <i>R</i> \$510.20	X
1 pc	Rear boot rubber	<i>74.85 in</i> <i>with</i> \$149.70	<i>50 in</i>
1 pc	Rear end panel <i>485-10</i>	<i>At</i> \$527.40	✓
1 pc	Rear end panel inner garnish	<i>my car</i> \$85.60	✓
2 pcs	Rear fender inner trim <i>e 267-</i>	<i>all 2ats</i> \$405.20	✓
1 pc	Rear bumper <i>184</i>	<i>At</i> \$525.60	✓
2 pcs	Rear bumper side retainer	\$55.00 <i>in</i> \$110.00	X
1 pc	Rear bumper reinforcement	<i>At</i> \$282.80	✓
1 pc	Rear bumper sponge <i>119</i>	<i>car</i> \$185.70	✓
1 pc	Rear spare tyre panel	<i>Return</i> \$955.10	X
1 pc	Rear spare tyre cover board	<i>in</i> \$142.50	✓
1 pc	Spare tool sponge	<i>in</i> \$118.20	X
1 pc	Rear exhaust silencer	<i>in</i> \$655.70	X
			\$8,024.60
			Less 20 %
			\$1,604.92
			balance c/f
			\$6,419.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SZ 2489 R

S. Nett Item

balance b/f \$6,419.68

1 pc Rear no plate
1 set Rear reverse sensor
20 pcs Clip

in \$45.00 *x*
nd \$200.00 *—*
\$2.00 *in* \$40.00 *—*
\$285.00

Labour Charges

Remove/renew the above parts including knocking, cutting & welding

700
\$1,200.00

To putty & spray paint on rear accident affected portion.

\$1,200.00 *800*

Check/reconnect wiring.

\$45.00 *201*

To spray anti rust on accident affected portion.

\$150.00 *601*

Remove/refit rear boot upholstery to facilitate repair.

\$100.00 *601*

Remove/renew rear exhaust silencer.

in \$180.00 *x*
Total \$9,579.68