

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Sep-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6202 J

1 pc	Rear bumper	\$ 696.00	Xr
1 pc	Rear bumper lower cover	\$ 206.00	/scr
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$ 58.00	X Scr
1 pc	Rear bumper n/s reflector	\$ 46.00	/scr
		\$ 1,006.00	
		Less 10%	\$ 100.60
			\$ 905.40

### S/NETT

1 set	Rear bumper clips	\$ 48.00	/ncc
1 set	Reverse sensor	\$ 280.00	2700 cat
1 set	Bootlid stickers	\$ 30.00	/ncc
	Sundry	\$ 50.00	X Scr
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	300 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	40
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 650.00	400 180
	To putty and spray painting on bootlid lower garnish, rear bumper	\$ 400.00	180
		\$ 2,663.40	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

F: \$750

Thuan@Lhauto.com

82235769

2days wp

21/9/21 1430

L/S after repair photo

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: