Our Ref: GB

GBE7523L21094

Date: 13/10/2021

Your Ref:

China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909

Attn: Motor Claims Department	
Dear Sir / Madam	
Traffic Accident Along Bukit Batok Avenue 6 Involving GBE7523L and PC1122U On 14/09/2021	_
We/I, Goldbell Leasing Pte Ltd (NRIC / ROC No: 199001196N), the registry of the above accident. Our/my China Taiping authorized appraiser and we / I based our / my claims S\$ 7,200-00 being the repair for 10 Days (Strictly on a Without I we/I have ascertained that you were the insurers of the driver of m/vehicl same was involved in the aforesaid accident with our/my m/vehicle - GB	vehicle was surveyed by ' on his recommendation for Prejudice Basis).
We/I whereby you are the insurers of m/vehiclePC1122U and the drive by the negligence of your insured and as a result there of our / my m/vehicle suffered loss and damage as follows:	er/owner was caused solely cle - <u>GBE7523L</u> has
Cost of repairs S\$ LOU for pre-repair notice 02 days @ S\$ 80-00 [2986 cc] LOU Fee for10 days @S\$ 80-00 [2986 cc] Rental Fee Invoice No:	7,200-00 160-00 800-00
GIA / LTA search fee Towing Fee (Cash Sale No) Survey Fee	2-00
Total Amount S\$	8,162-00
We/I enclose herewith copies of the supporting documents for vehicle no. (i) Motor Accident Report & Documents; (ii) Repair Invoices;	GBE7523L as follows:-
Kindly look into the matter and let us/me hear from you on the settlemen as possible.	t of our/my claims as soor
Please remit us/me your settlement sum in favor of M/s Liu's Brother Ar Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Thank you.	uto Engineering Workshop Bukit Singapore 417883.
Yours faithfully,	

The owner of m/vehicle GBE7523L

Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engineering Workshop



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@ymail.com

Invoice/Ref No: GBE7523L210914

Final Bill

13-10-21

Customer
Name: China Taiping Insurance (Singapore) Pte Ltd
Date:

Address: Motor Claims Department
3 Anson Road #16:00

Vehicle No: GBE7523L

Model/Make: Toyota Hiace

	Springleaf Tower Singapore 079909			l odel/Mak Van Turbo			ota Hi	ace
	Springlear Tower Singapore 079909		i		الر ق	1		
Item No.	Descriptions Of Parts			Original Quotation Estimation				rised ation / f Repai
1	Rear Tailgate		1 [\$ 1,956.20			\$	-
2	Tailgate Lock		П	\$ 394.90)	1	\$	-
3	Tailgate Rubber		Ш	\$ 455.00		1	\$	-
4	Tailgate Inner Trim Board		П	\$ 195.80		1	\$	-
5	Tailgate Inner Trim Board Clips 1 set		Ш	\$ 50.00	SI	1	\$	
6	Tailgate Windscreen Moulding		П	\$ 219.00		1	\$	-
7	Tailgate Windscreen Sealant			\$ 50.00	SN	1	\$	-
8	Tailgate " Toyota Logo" Motif			\$ 167.00		ı	\$	•
9	Tailgate "HIACE" Emblem			\$ 105.00	1	1	\$	-
10	Tailgate "70 KM/H" Sticker			\$ 15.00		1	\$	-
11	Tailgate "8 PAX" Sticker	J	,	\$ 15.00	SN		\$	•
12	Tail Lamp 02 pcs (@ S\$365.10)			730.20	1		\$	
13	Tail Lamp Panel Lh			435.20			\$.
14	Corner Panel Lh		1	376.50			\$.
15	Corner Panel Bracket Lh	- 1		31.50			\$.
16	Fender (Body Panel) Lh		1 1	1,308.10			\$	-
17	End Panel Outer		1			1		-
18	End Panel Inner		1			1		-
19	End Panel Sealant	- 1	1		SN	\$.
20	Floor Panel Beam	- 1	\$			\$.
21	Floor Board (Plywood)	1	\$		SN	\$.
22	Bumper	- 1	\$			\$.
23	Bumper Clips 1 set		\$		SN	\$.
24	Bumper Reverse Sensor		\$		SN	\$:
25	Bumper Bracket 02 pcs (@ S\$78.10)		\$			\$.
26	"Corporate" Advertisement & Artwork Sticker		\$	300.00	SN	\$.
	To check all wiring & electrical component for proper funct	ion	\$	50.00	- 1	\$.
	Remove and refix rear Bumper distance sensor	- 1	\$	90.00		\$.
	Remove & reinstall Windscreen Glass to facilitate repairs &	perform water		120.00		\$.
	Remove and refix rear tailgate components & wiper mechan	nism	\$	80.00		\$.
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing	g Parts Etcs	\$	1,800.00		\$.
	To putty & spray painting & including touch up paint on a	ccident affected	\$	200.00		\$.
	To apply Rust Proofing , reseal tuff-coating treatment on ac	cident area	\$	80.00	L	\$		
			_	19 260 40				

Total Parts & Labour of estimate for damaged vehicle

Total amount in Lump Sum Basis for repaired vehicle

12,005.40

SDLS: Seven Thousand Two Hundred Only

\$ 7,200.00

INSURER ENQUIRY Find insurer Vehicle reg. no.

PC1122U

Date of Accident

14/09/2021 🗰

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance China Taiping Insurance (Sing... Period of Insurance 22/05/2021 - 21/05/2022 Requested By Susan Low (Liu's Brother Auto... Requested Date 21/09/2021 09:13

Payment details

Request Amount: **\$\$1.87**GST Amount: **\$\$0.13**Total Amount Due (GST Inclu

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: **M400017735**