



Sin Ming Autocare BFG Pte Ltd

176 Sin Ming Drive
 #02-05 Sin Ming Autocare
 Singapore 575721
 Tel : 6455 0600 | Fax : 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

CHINA TAIPING INSURANCE (S) PTE LTD

Attn: Motor Claim Dept

ESTIMATE

VEHICLE NO: SJU1380S
 MAKE/MODEL: TOYOTA ALTIS
 ELEGANCE
 DATE: 20/09/2021

No.	Descriptions	Qty	Unit Price	Amount S\$
LIST ITEM:				
1	BOOT LID	1	\$ 1,407.64	\$ 1,407.64
2	BOOT HINGE LH	1	\$ 85.20	\$ 85.20
3	BOOTLID WEAHTERSTRIP	1	\$ 268.40	\$ 268.40
4	BOOT OUTER GARNISH	1	\$ 268.40	\$ 268.40
5	BOOT LOCK	1	\$ 385.25	\$ 385.25
6	BOOT EMBLE "LOGO"	1	\$ 85.60	\$ 85.60
7	BOOT EMBLE "COROLLA"	1	\$ 72.50	\$ 72.50
8	BOOT EMBLE "ALTIS"	1	\$ 85.60	\$ 85.60
9	BOOTLID INNER TRIM	1	\$ 320.80	\$ 320.80
10	BOOT INNER TRIM CLIP	4	\$ 10.00	\$ 40.00
11	TAIL LAMP RH	1	\$ 615.84	\$ 615.84
12	TAIL LAMP LH	1	\$ 615.84	\$ 615.84
13	TAIL LAMP PANEL	1	\$ 180.50	\$ 180.50
14	REAR BODY PANEL	1	\$ 871.00	\$ 871.00
15	REAR BODY PANEL TOP GARNISH	1	\$ 324.20	\$ 324.20
16	SPARE WHHEL PANEL COVER	1	\$ 450.15	\$ 450.15
17	REAR FENDER LH	1	\$ 1,082.80	\$ 1,082.80
18	REAR FENDER INNER TRIM RH	1	\$ 444.90	\$ 444.90
19	REAR BUMPER	1	\$ 795.60	\$ 795.60
20	REAR BUMPER BRACKER LH / RH	2	\$ 128.40	\$ 256.80
21	REAR BUMPER SIDE RETAINER LH / RH	2	\$ 128.40	\$ 256.80
22	REAR BUMPER REFLECTOR RH / LH	2	\$ 75.60	\$ 151.20
23	REAR WHEEL BEARING LH	1	\$ 485.35	\$ 485.35
24	REAR BUMPER REFLECTOR RH	1	\$ 75.60	\$ 75.60
25	REAR BOOTLID REFLECTOR RH	1	\$ 192.40	\$ 192.40
26	REAR BOOTLID EMBLEM "1.6VVTI"	1	\$ 85.60	\$ 85.60
27	REAR BUMPER SPONGE	1	\$ 185.00	\$ 185.00
				\$ 10,088.97

SPECIAL NETT ITEMS:

1	REAR NUMBER PLATE	\$	50.00	\$	50.00
2	REAR NUMER PLATE HOLDER	\$	30.00	\$	30.00
3	REVERSESENSOR LH/RH	\$	300.00	\$	300.00
4	REAR CAMERA	\$	480.00	\$	480.00
					\$ 860.00

LABOUR:

1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT ON AFFECTED AREAS.	\$	1,800.00	\$	1,800.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT EFFECTED PORTION.	\$	1,200.00	\$	1,200.00
3	TO APPLY RUST PROOFING ON REPAIR, REPLACE PANEL.	\$	180.00	\$	180.00
4	LABOUR TO REMOVE AND REPLACE REAR BOOTLID.	\$	80.00	\$	80.00
5	TO CHECK WIRING FUNCTIONS.	\$	80.00	\$	80.00
					\$ 3,340.00