

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4 #01-49
 SINGAPORE 415875
 TEL: 64524457 FAX: 64524584
 ATT: IKHWAN HP 93290237

Estimate for SLF9164C(Honda Civic)

2016

- 1 *FACE ASSYRR.BUMPER
- 1 *SPACERR.RR.BUMPER SIDE
- 1 *SPACERL.RR.BUMPER SIDE
- 1 *GARNISHRR.BUMPER LOWER
- 1 *GARNISHL.RR.BUMPER SIDE
- 1 *GARNISHR.RR.BUMPER SIDE
- 1 *COVERR.FINISHER
- 1 *COVERL.FINISHER
- 1 *REFLECTOR ASSYR.RR.
- 1 *REFLECTOR ASSYL.RR.
- 1 *BEAM COMPRR.BUMPER
- 1 *TAILLIGHT ASSYR.
- 1 *TAILLIGHT ASSYL.
- 1 *BRACKETR.RR.BUMPER SIDE
- 1 *BRACKETL.RR.BUMPER SIDE
- 1 *TAILLIGHT ASSYL.
- 1 *TAILLIGHT ASSYR.
- 1 *BRACKETL.RR.BUMPER SIDE
- 1 *BRACKETR.RR.BUMPER SIDE
- 1 *LID COMP TRUNK
- 1 *HINGE COMPR.TRUNK
- 1 *HINGE COMPL.TRUNK
- 1 *EMBLEM
- 1 *EMBLEM SETRR
- 1 *PANEL SETRR
- 1 *OUTLET ASSYRR.AIR
- 1 *STIFFENER,R.RR.PANEL SIDE
- 1 *STIFFENER,I.RR.PANEL SIDE
- 1 *4PCS ACT RR.SENSOR

617.20 \$717.20 DDV ✓
 ✓ \$31.50 } NECV ✓
 ✓ \$31.50 }
 ✓ \$35.30 BR ✓
 \$17.60 } NSX
 \$17.60 }
 \$21.90 NDX
 ✓ \$21.90 BR ✓
 \$17.00 NDX
 ✓ \$17.00 BR ✓
 ✓ \$199.00 BT ✓
 ✓ \$253.80 } BR ✓
 ✓ \$253.80 }
 ✓ \$12.20 } BR ✓
 ✓ \$12.20 }
 \$373.10 } RPTX
 \$373.10 }
 \$12.20 } RPTX
 \$12.20 }
 ✓ \$572.10 DDV ✓
 \$43.50 } NDX
 \$43.50 }
 ✓ \$23.50 } NECV
 ✓ \$11.50 }
 ✓ \$436.00 DDV ✓
 \$27.80 NSX
 \$126.00 } NDX
 \$126.00 }
 200.00 \$320.00 SCV

Less 20%

2728.50 \$4,160.00
 545.70 \$832.00
 2182.80 \$3,328.00

- *REAR BUMPER CLIP
- *BOOTLID INNER TRIM CLIP

30.00 \$50.00 } NECV ✓
 30.00 \$50.00 }
 60.00 \$100.00

- TO CHECK REAR ELECTRICAL WIRING
- TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR
- TO RESPRAY UNDERCOATING
- TO RESPRAY PAINTING AND ETC

60.00 \$50.00 NNX
 60.00 \$120.00 NECV ✓
 60.00 \$80.00 NNX
 600.00 \$1,000.00

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Supplementray for SLF9164C(Honda Civic)

*PANEL SETL.RR.TRIM

*PANEL SETR.RR.TRIM

Less 20%

*REAR FENDER TRIM CLIPS

Total

176.00	\$368.80	} BR ✓
176.00	\$368.80	
	\$737.60	
	\$147.52	
	\$590.08	

\$100.00	60.00 NEL ✓
\$100.00	

\$690.08

Resurvey

27/9/2021

14/10/21

TG Lim MW

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS

\$1,000.00

600.00 ✓

\$2,250.00

Total

\$5,678.00

Survey & Resurvey

21/9/2021

1515hrs

TG Lim

Lamp Screen repair

Repair days 6

6368.08

Parts 2464.40

SN 1120.00

Labour 1260.00

3844.40

@ 20% 768.88

3075.52

L/S 3050/2

L/S 3050/2

TG Lim

2/10/2021

NV 26,318/2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: