

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Christina Wong

Date: 02 Mar 2022

## **Preliminary Advice**

Insured	: SDY453Y		
Vehicle No			
TP Vehicle No	: SJZ2597B	Accident Date	: 17/09/2021
Make	: TOYOTA CAMRY	Assignment Date	: 21/09/2021
Date of Inspection	: 22/09/2021	Est. Duration of Repair	: 7
Inspection At	: AP AUTOMOTIVE SERVICES PTE LTD 56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,407.25
Revised Amount	:S\$	11,983.97
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,983.97

Lump Sum Repair	:S\$	9,550.00
-----------------	------	----------

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	16,439.00

Salvage Value	:S\$	
Margin for Repair	:S\$	18,561.00

**Remarks**

- ( ) The vehicle is economical for repair
  - ( ) The vehicle is not economical for repair
  - ( ) Part-by-Part repair
  - ( X ) Lump Sum repair
- 
- ( X ) The above survey was conducted on a 'without prejudice' basis.