

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21009862/VUF3N2**Date:** 09/10/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT108397
Claimant Vehicle No :	SHD6635M	Insured Vehicle No :	SGK9877L
Date of Loss:	19/09/2021	Nature of Claim:	TP
		Claim No:	M2104384

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6635M		
Make & Model:	MERCEDES-BENZ E220 BLUETEC, 2.1 D (A)	Engine No:	65192433262924
Reg. Date:	23/03/2016 (Man. Year: 2015)	Chassis No:	WDD2120012B316538
Colour:	White	Odometer:	701617 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,042.00	1,458.00	1,584.00	52.07
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,020.00	690.00	330.00	32.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,073.00	2,159.00	1,914.00	46.99
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,073.00	1,550.00	2,523.00	61.94
+ GST 7.00/7.00% (S\$)	285.11	108.50	176.61	61.94
Nett Amount (S\$)	4,358.11	1,658.50	2,699.61	61.94

INSPECTION

Date of Assignment:	21/09/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	21/09/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2021)

Parts: 143 MERCEDES-BENZ E220 BLUETEC 2.1 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6635M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Cut	1,510.00 FL	-	*1,510.00 FL
2	1		*REAR BUMPER LOWER COVER	Serviceable	325.00 FL	-	*- FL
3	2		*REAR BUMPER LOWER BRACKET RH/LH	Serviceable	270.00 FL	-	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	1,150.00 FL	-	*- FL
5	1		*REVERSE SENSOR	Cut	388.00 F	-	*200.00 FS
6	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,693.00	1,760.00
- List Item Discount on L Items 20.00/20.00% (\$)	651.00	302.00
Total Parts (\$)	3,042.00	1,458.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	400.00
2	SPRAY PAINTING	New	400.00	250.00
3	R/I REVERSE SENSOR	New	120.00	40.00
			Gross Labour Cost (\$\$)	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >