

Our Job Ref No : 305487677
 Date : 27/09/21

ENGINEERING
 ComfortDeliGro Engineering Pte Ltd
 59 Loyang Drive, Singapore 504389
 Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD6635M

Date of Accident : 19.09.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SGK9877L

2. The finalized amount shall be:

(a) Spare Parts after List discount _____

(b) Labour Charges _____

Total for Part-By-Part Repair Cost _____

(c.) Lumpsum Repair (if applicable) _____

Total for Lumpsum repair cost after Less: 20% \$1,550.00

Final Lumpsum Repair cost \$1,550.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 4/10/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: _____

TS

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 Sep 2021)
Parts: 143 **MERCEDES-BENZ E220 BLUETEC 2.1 D (A)** (Catalogue.Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHD6635M/21/09/2021 10:33
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER			
2	1		*REAR BUMPER LOWER COVER	20.00	0.00	*1,510.00 FL / Cat
3	2		*REAR BUMPER LOWER BRACKET RH/LH	20.00	0.00	*325.00 FL X SUC
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*270.00 FL X SUC
5	1		*REVERSE SENSOR	20.00	0.00	*1,150.00 FL n.Xr
6	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	*388.00 F 200 CUT
				0.00	0.00	*50.00 F / MIC
Sub Total (S\$)						3,693.00
- List Item Discount on L Items (S\$)						651.00
Total Parts (S\$)						3,042.00

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD6635M/21/09/2021 10:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	500.00 <i>400</i>
2	SPRAY PAINTING	New	400.00 <i>250</i>
3	R/I REVERSE SENSOR	New	120.00 <i>40</i>
Gross Labour Cost (S\$)			1,020.00

ComfortDelGro Engineering Pte Ltd/SHD6635M/21/09/2021 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuvan@lkhauto.com
82235769
2 days wp
L/S after repair photos
21/9/21 1630

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: