

AIG

TeamWork Garage Pte Ltd 53 Ubi Avenue 1 #01-23/24 Spore 408934 Pava Ubi Industrial Park

Tel: 6844 2475

E-mail: claims@teamworkgarage.com

ROC number: 201015366H REPAIR PERFORMA INVOICE

Vehicle number SLN1684D

Make / Model HONDA FIT

Chassis number GK31220028

Accident date

15/9/21

Reference

2109-35

			_	
Qty	Particulars		Unit Price - SGD \$	
	PARTS REPLACEMENT - LIST ITEMS		/0	f got (#9/5.20 255.20 (ut
1	FRONT DOOR PANEL RH		1211.98	286.70
1	FRONT DOOR HANDLE RH		441.20 AM J	Cut
1	FRONT DOOR WEATHERSTRIP		102.30 Marin V	144
1	FRONT DOOR TAPE		51.80	NEC
1	REAR DOOR PANEL RH		1011.80 K	21.60
1	RH WING MIRROR ASSY		51.80 RF 1011.80 RF 851.20 / CAT MG/ 79.53 / prefin	14 545 >195
1	RH WING MIRROR COVER		79.53 J brother	
			3749.81	
		Less 20%	749.97	
			2999.84	
	LABOUR AND MISCELLANEOUS CHARGES			
1	CHECK WIRING SYSTEM		60.00 20	
2	REMOVE & REFIT FRONT DOOR MECHANISM & TRIMS		200.00	
3	REMOVE & REFIT REAR DOOR MECHANISM & TRIMS		200.00 50 40×	
4	PANEL BEATING ON AFFECTED AREAS		1000.00400	
5	SPRAY PAINTING ON AFFECTED AREAS		1000.00 W ^O	
6	APPLY ANTI RUST ON AFFECTED AREAS		150.00 3 0	
		Subtotal	2610.00	
	Gr	and total	5609.84	

Thurn@Lkhauto.6m
82235769
3days wp
L/S bun 1th point photos
22/9/2/ 1300

F:\$1950

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: