

AIG

Vehicle number	SLN1684D ✓
Make / Model	HONDA FIT
Chassis number	GK31220028
Accident date	15/9/21
Reference	2109-35

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT DOOR PANEL RH	1211.98 ✓ def 804.6
1	FRONT DOOR HANDLE RH	441.20 ✓ 285.20
1	FRONT DOOR WEATHERSTRIP	102.30 ✓ cut
1	FRONT DOOR TAPE	51.80 ✓ NEC
1	REAR DOOR PANEL RH	1011.80 KR
1	RH WING MIRROR ASSY	851.20 ✓ get broken 345
1	RH WING MIRROR COVER	79.53 ✓ broken
		3749.81
	Less 20%	749.97
		2999.84
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING SYSTEM	60.00 20
2	REMOVE & REFIT FRONT DOOR MECHANISM & TRIMS	200.00 40
3	REMOVE & REFIT REAR DOOR MECHANISM & TRIMS	200.00 40X
4	PANEL BEATING ON AFFECTED AREAS	1000.00 400
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00 400
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2610.00
	Grand total	5609.84

thuan@lkkauto.com
82235769
3 days w p
L/S before paint photos
22/9/21 1300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: