



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M03DZ5

Date: 28th Sep 2021

Our Ref: CS3/ASM21007806/Btce2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Ang Yvonne

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKK 6833K

INSURED VEHICLE: SHC 2375U

ACCIDENT DATE: 17/07/2021

We thank you for your instruction on 21/09/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKK 6833K from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement and Police Report of Vehicles SKK 6833K and SHC 2375U.
- c) Final Repair Bill of SKK 6833K from M/s Yap Motor Service Ptd Ltd.
- d) Colour damaged vehicle photographs of SKK 6833K.

Pre-Repair Inspection Date : 26/07/2021 at M/s Yap Motor Service Pte Ltd, Blk 7 Sin Ming Ind Est Sec C #01-80 & 82, Singapore 575642.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKK 6833K
Make & Model	: Mercedes Benz E200 Exclusive (R18 LED)
Year of Registration	: 2017
Chassis Number	: WDD2130422A205628
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.