

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009871/GPS3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900112346
Claimant Vehicle No :	SKB9627S	Insured Vehicle No :	SJX249E
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	1276569946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB9627S		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI 1T32B4 (A)	Engine No:	CAV314088
Reg. Date:	13/07/2011 (Man. Year: 2011)	Chassis No:	WVGZZZ1TZBW105871
Colour:	Grey	Odometer:	130848 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,115.98	1,318.50	1,797.48	57.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,400.00	260.00	15.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,775.98	2,718.50	2,057.48	43.08
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	4,775.98	2,150.00	2,625.98	54.98
+ GST 7.00/7.00% (S\$)	334.32	150.50	183.82	54.98
Nett Amount (S\$)	5,110.30	2,300.50	2,809.80	54.98
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		2,660.50		
Liabile Amount (50.00%) (S\$)		1,330.25		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,332.25		
Global Sum Settlement (S\$)		1,330.00		

INSPECTION

Date of Assignment:	21/09/2021		
Date Inspected:	20/10/2021	Inspected At:	Vin's Motor Pte Ltd 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Buckled	1,250.00 FL	*1,250.00 FL
2	1		*FRONT RH DOOR OUTER CHROME MOULDING	Not Necessary	75.00 FL	*- FL
3	1		*FRONT RH DOOR OUTER GARNISH	Cut	110.00 FL	*110.00 FL
4	1		*FRONT RH DOOR HANDLE	Repair	284.20 FL	*- FL
5	1		*REAR RH DOOR	Repair	1,220.00 FL	*- FL
6	1		*REAR RH DOOR OUTER CHROME MOULDING	Not Necessary	68.00 FL	*- FL
7	1		*FRONT RH DOOR OUTER GARNISH	Cut	105.00 FL	*105.00 FL
8	1		*FRONT RH DOOR UPPER HINGE	Not Necessary	135.00 FL	*- FL
9	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	215.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,462.20	1,465.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	346.22	146.50
Total Parts (\$\$)	3,115.98	1,318.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR DAMAGES	New	780.00	600.00
2	TO RESPRAY PAINTING	New	880.00	800.00
			Gross Labour Cost (S\$)	1,400.00
			1,660.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >