



AUTOMOTIVE GROUP

▲ Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
☎ 6453 2121 (4 lines) / 6458 1111 (24 hrs)  
☎ 6459 9795 / 6459 0433  
✉ admin@vinsautogroup.com.sg  
🌐 www.vinsautogroup.com.sg

Our Ref : TP  
Accident date: 17/9/2021  
Your Ref : SJX249E

Tax Invoice :  
Date : 22/9/2021

MOTOR CLAIM DEPARTMENT  
AIG ASIA PACIFIC INSURANCE PTE LTD  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKB9627S  
Model : Volkswagen TOURAN 1.4L AT TSI IT32B4

1	pc	Front RH door	✓ free		\$ 1,250.00
1	pc	Front RH door outer chrome moulding	X	cut	\$ 75.00
1	pc	Front RH door outer garnish	✓	cut	\$ 110.00
1	pc	Front RH door handle	X	repair	\$ 284.20
1	pc	Rear RH door	?		\$ 1,220.00
1	pc	Rear RH door outer chrome moulding	X	cut	\$ 68.00
1	pc	Rear RH door outer garnish	✓	cut	\$ 105.00
1	pc	Rear RH door upper hinge	X		\$ 135.00
1	pc	Rear RH door lower hinge	X		\$ 215.00
					<hr/>
					\$ 3,462.20
Less 10%					-\$ 346.22
					<hr/>
					\$ 3,115.98

To repair damages  
To spray painting

\$ 780.00 600  
\$ 880.00 800  

---

---

\$ 4,775.98

VIN'S MOTOR PTE LTD

5 Days.  
part by part.  
before part photo.  
Gino Qiang  
20/10/2021

**LHK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged: \_\_\_\_\_  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_