



AUTOMOTIVE GROUP

▲ Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
☎ 6453 2121 (4 lines) / 6458 1111 (24 hrs)
☎ 6459 9795 / 6459 0433
✉ admin@vinsautogroup.com.sg
🌐 www.vinsautogroup.com.sg

Our Ref : TP
Accident date: 17/9/2021
Your Ref : SJX249E

Tax Invoice :
Date : 22/9/2021

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKB9627S
Model : Volkswagen TOURAN 1.4L AT TSI IT32B4

1	pc	Front RH door	Free	\$	1,250.00	✓
1	pc	Front RH door outer chrome moulding	X	\$	75.00	
1	pc	Front RH door outer garnish	Cut	\$	110.00	✓
1	pc	Front RH door handle	X Repair	\$	284.20	
1	pc	Rear RH door	X Repair	\$	1,220.00	
1	pc	Rear RH door outer chrome moulding	X	\$	68.00	
1	pc	Rear RH door outer garnish	Cut	\$	105.00	✓
1	pc	Rear RH door upper hinge	X	\$	135.00	
1	pc	Rear RH door lower hinge	X	\$	215.00	
				\$	3,462.20	1465
Less 10%				-\$	346.22	
				\$	3,115.98	1318.5
To repair damages				\$	780.00	600
To spray painting				\$	880.00	800
				\$	4,775.98	
					2718.5	
					-20%: 2150	

VIN'S MOTOR PTE LTD

5 Days.
part by part.
before part photo.
Gino Qiang
20/10/2021

LHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged: _____
Signature: _____
Date: _____