



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name LCV13218/Mr Tang Minjin, Kiefer
Contact No	Reg No/Reg Date SMW475M / 30/10/2020
	Date In/Mileage 21/09/2021/ 10501
	Chassis No KNAD6811VL6413377
	Engine No G3LCKP206862
	Make/Model KIA/STONIC 1.0 A
	Colour/Trim EU3 / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	21/09/2021/ 15:02	DS	218 / Mars Ler	19079

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS			^^	100.00
S MIPNT88088 TO REPLACE FRONT UPR & LWR BUMPER,ETC STRAGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS			320	1280.00
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS			550	1100.00
M KS 86511 H8 400 UPR COVER-FR BUMPER	1.00	476.00	0.00	476.00
M KS 14160 03 183 RIVET	4.00	1.00	0.00	4.00
M KS 86520 H8 400 ABSORBER-FRONT BUMPER	1.00	98.00	0.00	98.00
M KS 86512 H8 400 LWR COVER-FR BUMPER	3.00	367.00	0.00	367.00
P KS 06032 50 037A FASTENER- BUMPER	10.00	2.00	0.00	20.00
M KS 86513 H8 400 LH SIDE BRACKET-FR B	1.00	13.00	0.00	13.00
M KS 86514 H8 400 RH SIDE BRACKET-FR B	1.00	13.00	0.00	13.00

Z NOTES

ACCIDENT ON 20/09/2021 ALONG SUNTEC CITY BASEMENT 2 CARPARK
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # SKE6363G TP INS : I.I.I

not Attached
24/9/21
2 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

Parts

Labour

Standard Menu

Specialist Job

Others (Lub, etc)

Sundry

Total (w/o GST)

991.00

0.00

0.00

2,730.00

0.00

0.00

3,721.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.