



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that Inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name LCV13218/Mr Tang Minjin, Kiefer Reg No/Reg Date SMW475M / 30/10/2020 Date In/Mileage 05/10/2021/ 10501 Chassis No KNAD6811VL6413377 Engine No G3LCKP206862 Make/Model KIA/STONIC 1.0 A Colour/Trim EU3 / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000036	Credit	07/10/2021/ 14:22	DS	218 / Mars Ler	19079			
Description of Goods/Services					Qty	Unit Price	Disc%	Amount

S	MIPNT88088							250.00
	DIAGNOSTIC / SCANNING							
S	MIPNT88088							320.00
	TO REPAIR FRONT BUMPER,ETC							
	STRAGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS							
S	MIPNT98088							550.00
	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS							
X	C1609267280	RIVET		4.00	1.00	0.00		4.00
X	KS 06032 50 037A	FASTERNER- BUMPER		10.00	2.00	0.00		20.00
Z	NOTES							
	ACCIDENT ON 20/09/2021 ALONG SINTIC CITY BASEMENT 2 CARPARK							
	OWNER CLAIMING THIRD PARTY							
	REQUIRED REPLACEMENT CAR (CHAN'S)							
	TP # SKE6363G TP INS : 1.1.1							

Estimate

Confirm & accepted by

Parts	24.00
Labour	0.00
Standard Menu	0.00
Specialist Job	1,120.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	1,144.00

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.