

FBE1147D

Accident along 31 Sungei Kadut Ave, Singapore 729660

S/N	Qty	Description	(S\$)
<u>Parts</u>			
1	1pcs	Front Mudguard - BR	\$ 75.00
2	1pcs	Front Wheel (Radiator) - BT	\$ 350.00
3	1pcs	Front Wheel Shaft 2 x nn	\$ 130.00
4	1pcs	Front Wheel Bearing 4 x nn	\$ 80.00
5	1pcs	Front Disc Rotor x nn	\$ 200.00
6	2pcs	Front Fork Assy LH & RH @240 - BT	\$ 480.00
7	1pcs	Stem Steering - BT	\$ 165.00
8	1pcs	Handlebar - BT	\$ 80.00
9	1pcs	Clutch Lever - BT	\$ 40.00
10	1pcs	Brake Lever x nn	\$ 40.00
11	2pcs	Balancer @25/pcs - CUT	\$ 50.00
12	2pcs	Side Mirror @30/pcs - CUT	\$ 60.00
13	1pcs	Front Headlamp Cover - BR	\$ 60.00
14	1pcs	Rear Headlamp Cover x nn	\$ 60.00
15	2pcs	Front Signal Lamp @25/pcs - BR	\$ 50.00
16	1pcs	Headlight Assy - CUT	\$ 160.00
17	1pcs	Front Mask - BR	\$ 90.00
18	1pcs	Front Mask Base - BR	\$ 120.00
19	1pcs	Pilot Light (Engine coil cover LH) - BR	\$ 250.00
20	1pcs	Belly shield covering x nn	\$ 90.00
21	1pcs	Front Side Fairing LH - BR	\$ 95.00
22	1pcs	Front Side Fairing RH - BR	\$ 95.00
23	1pcs	Rear Side Fairing LH - BR	\$ 95.00
24	1pcs	Rear Side Fairing RH - BR	\$ 95.00
25	1pcs	Centre covering x nn	\$ 120.00
26	1pcs	Front Footrest Bar - BT	\$ 75.00
27	2pcs	Front Footrest Rubber @45/pcs - CUT	\$ 90.00
28	1pcs	Gear Padal - BT	\$ 50.00
29	1pcs	Brake Pedal x nn	\$ 80.00
30	1pcs	Rear LH Foot Rest - CUT	\$ 45.00
31	1pcs	Rear LH Foot Rest Bracket x nn	\$ 80.00
32	1pcs	Exhaust pipe x nn	\$ 400.00
33	1pcs	Exhaust pipe cover x nn	\$ 65.00

Total \$ 4,015.00
 -10% \$ 401.50
 Parts Sub Total \$ 3,613.50

		Special Nett	
34	1pcs	Front fork seal - nec	\$ 80.00
35	1pcs	Front fork oil - nec	\$ 300.00
36	1pcs	Rear Box - CUT	\$ 350.00
37	1pcs	Rear Box Bracket - BT	\$ 150.00
38	1pcs	Lh Round Box x nn	\$ 120.00

	1pcs	IU Unit <i>x nn</i>	\$	160.00
39	1pcs	No. plate (front) <i>- BT</i>	\$	20.00
40	1set	Body sticker <i>- nec</i>	\$	180.00

Total \$ 1,360.00

Labour				
1		Towing	\$	100.00 <i>50</i>
2		To realign body frame	\$	350.00 <i>200</i>
3		To R&R front suspension, handle bar, headlamp, side fairing, and attachments.	\$	400.00 <i>200</i>
			Labour Total:	\$ 850.00
			Sub Total (labour and parts):	\$ 5,823.50

Vehicle is at **5 Soon Lee Street #01-38 Pioneer Point S(627607)**
Please arrange your surveyor to come down to survey the vehicle.
Contact : **Daryl 98356259**

Steve (LKK)

21/9/21

without Prejudice

4 days

L/S

Resurvey After Spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____