

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009875/UGS3Q2**Date:** 18/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJK5330M **Insured Vehicle No :** SMH758B
 Date of Loss: 09/09/2021 Nature of Claim: TP Claim No: MFL2021D0004094

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK5330M**
 Make & Model: MITSUBISHI LANCER, 1.5 GLX (A) Engine No: 4B11BR4204
 Reg. Date: 24/10/2008 (Man. Year: 2008) Chassis No: JMYSTCY4A8U004569
 Colour: Grey Odometer: 229436 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,054.20	2,531.20	2,523.00	49.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	930.00	550.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,534.20	3,461.20	3,073.00	47.03
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	6,534.20	2,700.00	3,834.20	58.68
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,027.45		

INSPECTION

Date of Assignment: 21/09/2021
 Date Inspected: 22/09/2021 Inspected At: Sin Hwee Motor Pte Ltd (HQ)
 Estimated Period of Repair: 3.0 days Blk 3023A, Ubi Road 1, #01-59
 Singapore 408717

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Dec 2021)

Parts: 143 MITSUBISHI LANCER 1.5 GLX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK5330M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	858.00 FN	*858.00 FN
2	1		*BUMPER SIDE BEAM	Not Necessary	79.00 FN	*- FN
3	1		*FRONT FENDER	Repair	588.00 FN	*- FN
4	1		*FENDER INNER COVER	Not Necessary	141.00 FN	*- FN
5	1		*HEADLAMP (HID)	Scratched	1,910.00 FN	*1,910.00 FN
6	1		*LOWER LIP	Repair	480.00 FN	*- FN
7	1		*KNUCKLE ARM	Not Necessary	554.00 FN	*- FN
8	1		*WHEEL BEARING	Not Necessary	428.00 FN	*- FN
9	10		*BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
10	1		*SPORT RIM	Repair	480.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	5,558.00	2,808.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	503.80	276.80
Total Parts (\$)	5,054.20	2,531.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK INNER BRACKET AND REPLACE ,INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC	New	550.00	300.00
2	TO SPRAY PAINT FRONT BUMPER ,LOWER LIP AND FENDER	New	650.00	550.00
3	TO SUPPLY AND TUFF KOTE	New	120.00	0.00
4	TO CARRY OUT WIRE CHECKING	New	80.00	20.00
5	COMPUTER ALIGNMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			1,480.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >