

SIN HWEE MOTOR PTE LTD

ESTIMATE

*** Main Workshop ***

Blk 3023A Ubi Road 1 #01-59 S(408717)

*** Spray Paint Workshop @ Autobay ***

1 Kaki Bukit Avenue 6, #01-25 S(417883)

REG NO: 201327079M

MR LIM CHEE HIONG

DATE	21/9/2021
VEHICLE NO:	SJK 5330 M
MAKE:	MIT
MODEL:	LANCER

QUANTITY	DESCRIPTION	UNIT	AMOUNT
1 PC	FRONT BUMPER - NETT <i>Deep cut</i>	858.00	858.00 ✓
1 PC	BUMPER SIDE BEAM - NETT <i>un</i>	79.00	79.00 X
1 PC	FRONT FENDER - NETT <i>R</i>	588.00	588.00 X
1 PC	FENDER INNER COVER - NETT <i>un</i>	141.00	141.00 X
1 PC	HEADLAMP (HID) - NETT <i>scr</i>	1,910.00	1,910.00 /
1 PC	LOWER LIP - NETT <i>R</i>	480.00	480.00 X
1 PC	KUNCKLE ARM - NETT <i>un</i>	554.00	554.00 X
1 PC	WHEEL BEARING - NETT <i>un</i>	428.00	428.00 X
	----- SUBTOTAL		5,038.00
LESS 10%	----- LESS 10%	-10.00%	-503.80
10 PCS	BUMPER CLIP <i>un</i>	4.00	40.00 ✓
1 PC	SPORT RIM <i>R</i>	480.00	480.00 X
-	TO KNOCK INNER BRACKET AND REPLACE, INSTALL AND ALIGN AFFECTED PARTS TO SYMMETRICAL SPEC. <i>300</i>	550.00	550.00
-	TO SPRAY PAINT FRONT BUMPER, LOWER LIP AND FENDER <i>150</i>	650.00	650.00
-	TO SUPPLY AND TUFF KOTE <i>un X</i>	120.00	120.00
-	TO CARRY OUT WIRE CHECKING <i>20</i>	80.00	80.00
-	COMPUTER ALIGNMENT <i>60</i>	80.00	80.00

P-2768
 10%
 P-2491.2
 S.N-40.00
 L-930.00
 3461.20
 20%
 2768

not Adherent
new wheels
22/9/21
1/5 H 2700
when the after repair
3 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tel: 6745 5783 Fax: 6744 9582
 Email: sinhweemotor@gmail.com
 Website: www.sinhweemotor.com

TOTAL \$6,534.20