

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: CHINA TAPIING	<b>DATE</b>	: 21-Sep-21
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT</b>	:		
<b><u>VEHICLE DETAILS</u></b>			
<b>VEHICLE NO</b>	: SMY4426T		
<b>MODEL</b>	: HONDA FREED HYBRID 1.5G AUTO	<i>Asher.</i>	
<b>CHASSIS NO</b>			
<b><u>ACCIDENT DETAILS</u></b>	<b>DATE</b> : 19-Sep-21		
	<b>TIME</b> : 10:00 HRS		
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER <i>Regis</i>	1	\$ 1,050.40	\$ 1,050.40	+
2	FRONT BUMPER SIDE RETAINER <i>Regis</i>	2	\$ 58.40	\$ 116.80	+
3	FRONT FENDER <i>Regis</i>	2	\$ 322.00	\$ 644.00	+
4	FRONT FENDER EMBLEM <i>Regis</i>	2	\$ 55.90	\$ <del>111.80</del>	58
5	FRONT SIDE MIRROR COVER LH <i>Missing</i>	1	\$ 168.40	\$ 168.40	✓
6	FRONT SIDE MIRROR ASSY LH <i>Damage</i>	1	\$ 684.20	\$ 684.20	✓
7	FRONT DOOR LH <i>Regis</i>	1	\$ 742.00	\$ 742.00	+
8	FRONT DOOR HINGE <i>2</i>	2	\$ 90.00	\$ 180.00	+
9	FRONT DOOR CHECKER	1	\$ 103.00	\$ 103.00	+
10	FRONT DOOR LOCK <i>Al</i>	1	\$ 290.00	\$ 290.00	+
11	FRONT DOOR STICKER <i>Regis</i>	2	\$ 70.00	\$ 140.00	+
12	FRONT DOOR WEATHERSTRIP	1	\$ 190.00	\$ 190.00	+
13	POWER WINDOW REGULATOR	1	\$ 420.00	\$ 420.00	+
14	POWER WINDOW MOTOR	1	\$ 380.00	\$ 380.00	+

TOTAL PRICE \$ 5,220.60

LESS 20% \$ 1,044.12

**SUB TOTAL PRICE \$ 4,176.48**

910.60

728.48

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET)	1	\$ 20.00	\$ 20.00
2	HEADLAMP CLIPS(SET)	1	\$ 20.00	\$ 20.00
3	FRONT QUARTER GLASS SEALANT	1	\$ 40.00	\$ 40.00

**TOTAL \$ 80.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING ( FRONT)**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	700	
3	TUFF COAT	\$ 120.00	30	
4	WIRING CHECK	\$ 90.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 50.00	X	
6	REMOVE AND REFIX FRONT QUARTER GLASS	\$ 80.00	X	
7	TO REMOVE AND REFIX FRONT DOOR	\$ 60.00	X	

960

**TOTAL \$3,200.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 4,256.48  
 TOTAL LABOUR COST : \$ 3,200.00  
 TOTAL REPAIR COST : \$ 7,456.48

**APPROVED DETAILS**

**SURVEYOR :**  
**CONTACT NO :**  
**PART BY PART / LUMP SUM :**  
**NO OF DAYS :**

**FAX :**

Adrian Lj  
 P/P 21/09/21

030 w/s

total: 1688.48  
 (part by part)

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: