

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21009881/AUCN2**Date:** 16/11/2021**REFERENCE**

Insured/Claimant:	JEROSCHEWSKI ARNE	Policy No:	7210082049	
Date of Loss:	28/08/2021	Nature of Claim:	OD	Claim No: 6580441622SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNB315R</b>	Engine No:	DGK002656
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZFVXM2048563
Reg. Date:	28/07/2021 (Man. Year: 2020)	Odometer:	2458 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$230,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,061.00	1,990.16	7,070.84	78.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,152.00	3,102.00	3,050.00	49.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,213.00</b>	<b>5,092.16</b>	<b>10,120.84</b>	<b>66.53</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>14,213.00</b>	<b>4,092.16</b>	<b>10,120.84</b>	<b>71.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>994.91</b>	<b>286.45</b>	<b>708.46</b>	<b>71.21</b>
<b>Nett Amount (S\$)</b>	<b>15,207.91</b>	<b>4,378.61</b>	<b>10,829.30</b>	<b>71.21</b>

**INSPECTION**

Date of Assignment:	22/09/2021	
Date Inspected:	21/09/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-UPPER	Repair	2,397.00 FS	*- FS
2	1		*REAR BUMPER-LOWER	Repair	1,182.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Not Necessary	869.00 FS	*- FS
4	1		*REAR BUMPER CHROME TRIM-CENTER	Cut	269.00 FS	*215.20 FS
5	1		*REAR BUMPER TRIM-RIGHT	Not Necessary	115.00 FS	*- FS
6	1		*REAR BUMPER CLOSING ELEMENT-RH	Not Necessary	284.00 FS	*- FS
7	1		*REAR BUMPER EXHAUST CHROME TRIM-RH	Not Necessary	256.00 FS	*- FS
8	1		*REAR BUMPER TAIL LIGHT-RH	Cracked	699.00 FS	*559.20 FS
9	1		*REAR BUMPER CARRIER	Not Necessary	981.00 FS	*- FS
10	2		*REAR BUMPER CARRIER SEAL	Not Necessary	6.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP	Not Necessary	168.00 FS	*- FS
12	2		*REAR BUMPER PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
13	4		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
14	2		*REAR WHEEL ARCH TRIM-LH/RH	Necessary	1,166.00 FS	*932.80 FS
15	1		*REAR LID ADHESIVE	Necessary	19.00 FS	*14.88 FS
16	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
17	1		*Q5 EMBLEM	Necessary	99.00 FS	*79.04 FS
18	1		*QUATTRO EMBLEM	Necessary	99.00 FS	*79.04 FS
19	1		*REAR LID CHROME TRIM	Not Necessary	0.00 FS	*- FS
			(NPA)			
20	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>9,061.00      1,990.16</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR UPPER BUMPER,REAR LOWER BUMPER,REAR LID AND BOTH WHEEL ARCH TRIMS	New	4,000.00	2,050.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,152.00</b>	<b>3,102.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >