

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/752/2021/JT
DATE : 15-Sep-21
WIP : 44540

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

2-Nov-21

OWNER'S NAME : MR JEROSCHEWSKI ARNE
ADDRESS : 861 OLD HOLLAND ROAD
#01-16
SINGAPORE 278684
TELEPHONE : HP +65 9663882
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210082049
VEHICLE NO : **SNB 315 R**
MODEL CODE : AUDI Q5 LINE 2.0 TFSI
MODEL YEAR : 7/28/2021
ENGINE NO : DGK 002656
CHASSIS NO : WAUZZZFVXM2048563
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Aug-21
PLACE OF ACCIDENT : CORNER OF REDWOOD AVENUE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 315 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUCTION.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH WHEEL ARCH TRIMS.	\$	4,000.00	\$ 2,050.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	6,152.00	\$ 3,102.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 315 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 2,397.00	
2	REAR BUMPER - LOWER	1	\$ 1,182.00	
3	REAR BUMPER SPOILER	1	\$ 869.00	
4	REAR BUMPER CHROME TRIM - CENTER	1	\$ 269.00	\$ 215.20
5	REAR BUMPER TRIM - RIGHT	1	\$ 115.00	
6	REAR BUMPER CLOSING ELEMMENT - RH	1	\$ 284.00	
7	REAR BUMPER EXHAUST CHROME TRIM - RH	1	\$ 256.00	
8	REAR BUMPER TAIL LIGHT - RH	1	\$ 699.00	\$ 559.20
9	REAR BUMPER CARRIER	1	\$ 981.00	
10	REAR BUMPER CARRIER SEAL	2	\$ 6.00	
11	REAR BUMPER HOLDING STRAP	1	\$ 168.00	
12	REAR BUMPER PARKING AID SENSOR	2	TBC	
13	REAR BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00	
14	REAR WHEEL ARCH TRIM - LH / RH	1	\$ 1,166.00	\$ 932.80
15	REAR LID ADHESIVE	1	\$ 19.00	\$ 14.88
16	AUDI EMBLEM	1	\$ 138.00	\$ 110.00
17	Q5 EMBLEM	1	\$ 99.00	\$ 79.04
18	QUATTRO EMBLEM	1	\$ 99.00	\$ 79.04
19	REAR LID CHRIME TRIM	1	TBC	
20	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 9,061.00	\$ 1,990.16
TOTAL LABOUR CHARGES			\$ 6,152.00	\$ 3,102.00
GRAND TOTAL			\$ 15,213.00	\$ 5,092.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-01/11/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT