

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/752/2021/JT  
DATE : 15-Sep-21  
WIP : 44540

Hui Zhen.

\$5092.16.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR JEROSCHEWSKI ARNE  
ADDRESS : 861 OLD HOLLAND ROAD  
#01-16  
SINGAPORE 278684  
TELEPHONE : HP +65 9663882  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 7210082049  
VEHICLE NO : **SNB 315 R**  
MODEL CODE : AUDI Q5 LINE 2.0 TFSI  
MODEL YEAR : 28/7/2021  
ENGINE NO : DGK 002656  
CHASSIS NO : WAUZZZFYXM2048563  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 28-Aug-21  
PLACE OF ACCIDENT : CORNER OF REDWOOD AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 315 R**

| S/N                         | NATURE OF JOBS                                                                                                                | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS                                        |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------------------------------------------------------|
| 1                           | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUCTION.                                             | S/N \$ 360.00 ✓      |                                                                   |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 1,600.00 ✓        | 500 ✓                                                             |
| 3                           | TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH WHEEL ARCH TRIMS.                                          | \$ 4,000.00 ✓        | 2050 ✓<br>550 x 3 = 1650<br>Wheel Arc x 2 = 100 x 2 = 400<br>2050 |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                 | S/N \$ 192.00 ✓      |                                                                   |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                               | <b>: \$ 6,152.00</b> |                                                                   |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 315 R**

|                      |                                                        |     | DAMAGED PARTS & PRICES |          |
|----------------------|--------------------------------------------------------|-----|------------------------|----------|
| S/N                  | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS  |
| 1                    | REAR BUMPER - UPPER <i>2 Revis</i>                     | 1   | \$ 2,397.00            | X        |
| 2                    | REAR BUMPER - LOWER                                    | 1   | \$ 1,182.00            | +        |
| 3                    | REAR BUMPER SPOILER <i>Not in</i>                      | 1   | \$ 869.00              | +        |
| 4                    | REAR BUMPER CHROME TRIM - CENTER <i>Not in</i>         | 1   | \$ 269.00              | ✓ 215.20 |
| 5                    | REAR BUMPER TRIM - RIGHT <i>Not in</i>                 | 1   | \$ 115.00              | +        |
| 6                    | REAR BUMPER CLOSING ELEMENT - RH <i>2 Not in</i>       | 1   | \$ 284.00              | +        |
| 7                    | REAR BUMPER EXHAUST CHROME TRIM - RH                   | 1   | \$ 256.00              | +        |
| 8                    | REAR BUMPER TAIL LIGHT - RH <i>cracked</i>             | 1   | \$ 699.00              | ✓ 559.20 |
| 9                    | REAR BUMPER CARRIER <i>2 Not in</i>                    | 1   | \$ 981.00              | +        |
| 10                   | REAR BUMPER CARRIER SEAL                               | 2   | \$ 6.00                | +        |
| 11                   | REAR BUMPER HOLDING STRAP                              | 1   | \$ 168.00              | +        |
| 12                   | REAR BUMPER PARKING AID SENSOR <i>Not in</i>           | 2   | TBC                    | +        |
| 13                   | REAR BUMPER PARKING AID SENSOR SEAL RING <i>Not in</i> | 4   | \$ 14.00               | +        |
| 14                   | REAR WHEEL ARCH TRIM - LH / RH <i>Not in</i>           | 1   | \$ 1,166.00            | ✓ 932.80 |
| 15                   | REAR LID ADHESIVE <i>Not in</i>                        | 1   | \$ 19.00               | ✓ 14.88  |
| 16                   | AUDI EMBLEM <i>2</i>                                   | 1   | \$ 138.00              | ✓ 110.00 |
| 17                   | Q5 EMBLEM <i>1</i>                                     | 1   | \$ 99.00               | ✓ 79.04  |
| 18                   | QUATTRO EMBLEM                                         | 1   | \$ 99.00               | ✓ 79.04  |
| 19                   | REAR LID CHROME TRIM <i>Not in</i>                     | 1   | TBC                    | +        |
| 20                   | SUNDRIES <i>Not in</i>                                 |     | \$ 300.00              | X        |
| TOTAL SPARE PARTS    |                                                        | :   | \$ 9,061.00            |          |
| TOTAL LABOUR CHARGES |                                                        | :   | \$ 6,152.00            |          |
| GRAND TOTAL          |                                                        | :   | \$ 15,213.00           |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King  
SURVEYED DATE : 24/09/21  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, ~~03 Days~~ 04 Days.  
H.K.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT