

S/N	Qty	Description		(S\$)
Parts				
1	1pcs	Lh covering (Top) / CUT		
2	1pcs	Lh trimming / CUT	\$	100.00
3	1pcs	Lh bottom covering / CUT	\$	150.00
4	1pcs	Lh step board / CUT	\$	60.00
5	1pcs	Lh step board cover windshield / CUT	\$	230.00
6	1pcs	Handle bar / BT	\$ 150	117.00
7	1pcs	Lh side mirror / CUT	\$	120.00
8	1pcs	Lh brake lever / CUT	\$	85.00
9	1pcs	Lh balance / CUT	\$	75.00
10	1pcs	Lh tailboard / CUT	\$	60.00
11	1pcs	Main stand / CUT	\$	220.00
12	1pcs	Side stand / CUT	\$	150.00
13	1pcs	Air filter box / CUT	\$	120.00
			\$	250.00

Total \$ 1,737.00
 -10% \$ 173.70
Parts Sub Total \$ 1,563.30

Special Nett				
14	1pcs	Sticker "X Max" / N/C	\$	80.00
15	1pcs	Side stand adapter / CUT	\$	60.00
16	1pcs	Main stand adapter / CUT	\$	80.00
17	1pcs	Front fork oil / N/C	\$	80.00
18	1pcs	Front fork seal / N/C	\$	60.00

Total \$ 360.00

Labour				
1		To realign front fork	\$	150.00
2		To realign body frame	\$	300.00
3		To R&R front suspension, handle bar, headlamp, side fairing, and attachments.	\$	500.00
			Labour Total: \$	950.00

P-1051-70
 N-190
 L-400
 SUP-359
 2000-20
 L/S-1609.16
 = 1620

Sub Total (labour and parts): \$

2,873.30

Vehicle is at : 5 Soon Lee St, #01-38 Pioneer Point, Singapore 627607

Please arrange your surveyor to come down to survey the vehicle.

Contact: Daryl 9835 6259

Steve (LKK)
23/9/21, 2:00pm

WKL P/L
P/P
3 days
My Rep. by

LKK Auto Consultancy has been newly
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: