## FBR6403M

## Supplementary

S/N	Qty	Description				
					(S\$)	
		<u>Parts</u>				
1	1pcs	Exhaust pipe (L Repair) Cul BR		\$	450.00	100-
	1pcs	Exhaust pipe cover		\$	110.00	90-
	1pcs	Exhaust pipe tip BR		, \$	80.00	60-
	1pcs	Rh tail board cover (lower)		\$	130.00	110-
		•				•
			Total	\$	770.00	360
			-10%	\$	77.00	-10
			Parts Sub Total	\$	693.00	32
		Special Nett				
5	1pcs	Rear no plate <b>B</b> 1		\$	40.00	35-
			Sub Total :	\$	733.00	
						359
ehicle	e is at :	5 Soon Lee St, #01-38 Pioneer Point, Singapore 627607	ctore (1 K)	ച		

Vehicle is at: 5 Soon Lee St, #01-38 Pioneer Point, Singapore 627607 Please arrange your surveyor to come down to survey the vehicle.

Contact: Daryl 9835 6259

steve (LKK)