

A.S.S. REG. BY:

Steve

CS/AIG 21009882/ETF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

at:

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBR 6493M

Yr Regn:

27/8/20

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Xmax

CB

292

Colour:

Blue

A/O:

Insured / Std / NI / N

Sp. Reading

31233

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

MH 356 3910 LK 932-604

Gen. Cond: Good / Fair / Poor / Bupl

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-15

R:

140/70-14

BS / QUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYOTYOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

10/9/21

D.O.A.

23/4/21

Survey held at

Creation Motors

Des. of Damages: Frt / Rear / Q/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-17K

finalize \$1600 (L/S, before GST). 3 repair days.

RED:2006.30; 55%

Time, File, Retn to?

☐

: Prel. Report

☐

: Final Report

Time, File, Retn to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ - RS. \$1

Private

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (%)

☐

: Wash and

Time, File, Retn to?

Time, File, Retn to?

S/N	Qty	Description	(S\$)
Parts			
1	1pcs	Lh covering (Top) ✓ CUT	\$ 100.00
2	1pcs	Lh trimming ✓ CUT	\$ 150.00
3	1pcs	Lh bottom covering ✓ CUT	\$ 60.00
4	1pcs	Lh step board ✓ CUT	\$ 230.00
5	1pcs	Lh step board cover windshield ✓ CUT	\$ 150 117.00
6	1pcs	Handle bar ✓ RT	\$ 120.00
7	1pcs	Lh side mirror ✓ MT	\$ 85.00
8	1pcs	Lh brake lever ✓ CUT	\$ 75.00
9	1pcs	Lh balance ✓ CUT	\$ 60.00
10	1pcs	Lh tailboard ✓ CUT	\$ 220.00
11	1pcs	Main stand ✓ CUT	\$ 150.00
12	1pcs	Side stand ✓ CUT	\$ 120.00
13	1pcs	Air filter box ✓ CUT	\$ 250.00

Total \$ 1,737.00
-10% \$ 173.70
Parts Sub Total \$ 1,563.30

Special Nett			
14	1pcs	Sticker "X Max" ✓ MC	\$ 80.00
15	1pcs	Side stand adapter ✓ CUT	\$ 60.00
16	1pcs	Main stand adapter ✓ CUT	\$ 80.00
17	1pcs	Front fork oil ✓ MC	\$ 80.00
18	1pcs	Front fork seal ✓ MC	\$ 60.00

Total \$ 360.00

Labour			
1		To realign front fork	\$ 150.00
2		To realign body frame	\$ 300.00
3		To R&R front suspension, handle bar, headlamp, side fairing, and attachments.	\$ 500.00
Labour Total:			\$ 950.00

Sub Total (labour and parts): \$

2,873.30

Vehicle is at : 5 Soon Lee St, #01-38 Pioneer Point, Singapore 627607

Please arrange your surveyor to come down to survey the vehicle.

Contact: Daryl 9835 6259

Steve (LKK)
23/9/21, 2:00pm

WKL PL
P/P
3 days
My Bel My

LKK Auto Consultancy can certify

the Reparer of the following:

- To resurvey before labour is performed
- To display damaged parts during survey
- Parts prices are subject to market value
- Third party survey is on a 'no fault' basis
- No deposit needed on any work
- Supplementary fees for parts, labour and
is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date: