

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/09/2021

User ID PohSuan

Section A - Accident Details

Registration Number	SHF189M
Case Reference Number	TAX/09/21/2013
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHUA ENG HWEE
Type of Accident	Head to Rear
Accident Date and Time	8/9/2021 9:00 AM
Accident Reported Date and Time	8/9/2021 11:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112205
Special Instruction to ARC, if any	FRONT RIGHT
Prepared Date and Time	8/9/2021 5:53 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$1,296.00	\$450.00
Total Spare Part Cost	\$12,755.84	\$537.15
Total Other Cost	\$480.00	\$90.00
TOTAL COST	\$15,038.84	\$1,377.15 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Rasul / LKK
ARC / Surveyor Sign Off Date	08/09/2021 6:10 PM	10/09/2021 11:06 AM
Signature		
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2109-0270	Invoice Number	
Quotation Date	17.09.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$300.00
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,296.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given
		52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given
		52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Not Given
		52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Not Given
		81145-47890	UNIT , HEADLAMP , RH	0.00	\$2,637.60	0.00	\$0.00	Replace	Not Given
		81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given
		81210-12240	LAMP ASSY, FOG, RH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$472.40	0.00	\$0.00	Replace	Not Given
		51443-12110	COVER, ENGINE UNDER SIDE RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given
		53205-47900	SUPPORT S/A UPPER,	0.00	\$377.10	0.00	\$0.00	Replace	Not Given
		53202-47901	SUPPORT S/A RH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given
		53203-47901	SUPPORT S/A LH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given
		53028-12050	SUPPORT SUB-ASSY LOWER	0.00	\$409.90	0.00	\$0.00	Replace	Not Given
		53801-47080	FENDER SUB-ASSY, FR , RH	1.00	\$977.80	100.00	\$0.00	Replace	Repair

X
X
X
X
X
X
X
X
X
X
X
X
X
X
X
R

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/09/2021

User ID PohSuan

		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace	√
		53875-47120	LINER, FR FENDER, RH	0.00	\$202.50	0.00	\$0.00	Replace	Not Given	X
		53851-47061	PAD, FR WHEEL RH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given	X
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,879.40	100.00	\$0.00	Replace	Repair	R
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given	X
		52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Not Given	X
		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given	X
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$95.60	25.00	\$71.70	Replace	Replace	√
		52421-47040	PAD, FRONT BUMPER (NO.2)	0.00	\$36.00	0.00	\$0.00	Replace	Not Given	X
		52421-47030	PAD, FRONT BUMPER (NO.1)	0.00	\$40.70	0.00	\$0.00	Replace	Not Given	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	√
		51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
		53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Not Given	X
		53112-47310	GRILLE, RADIATOR	0.00	\$178.60	0.00	\$0.00	Replace	Not Given	X
		52127-47911	COVER, FR BUMPER RH	0.00	\$30.20	0.00	\$0.00	Replace	Not Given	X
		52116-47050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace	√
Total					\$15,595.64		\$537.15			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

537.15
 + 300.00
 + 540.00
 1,377.15