Auto Insure

Veron Chen (LKKAuto)

LTA: 14.391

From:

MV: 154,609

Rasul (LKKAuto)

Sent:

Friday, 18 February 2022 9:44 AM

To:

Veron Chen (LKKAuto)

Subject:

RE: URGENT ---- SNM21D205217C1 ---- XD98M Isuzu CYZ52K LKK REF:

CS/CTI21009887/R1vce2

Hi Veron,

Kindly wrote this,

was

I read the report and base on my finding, the vehicle sustained badly damage and was charred due to fire. I did took photos on both side front, internally and externally front portion as well as undercarriage.

I did not took more photos on the rear portion, accept only 1. It seems rear portion was not affected by the fire.

Reg Photos in GIA is some as design derage scen on on-site and also at at time of on inspection.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Figure 5 Save the Earth. Print only when necessary.

From: Veron Chen (LKKAuto)

Sent: Friday, 18 February, 2022 8:56 AM

To: Rasul (LKKAuto)

Subject: FW: URGENT ---- SNM21D205217C1 ---- XD98M Isuzu CYZ52K LKK REF: CS/CTI21009887/R1vce2

Hi Rasul,

As spoken, kindly assist- CS/CTI21009887/R1vce2

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Su Li (LKK Auto) < suli@lkkauto.com >

Sent: Wednesday, 16 February 2022 8:58 AM

To: Irene Tay < rene (LKKAuto) < veronchen@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Fw: URGENT ---- SNM21D205217C1 ---- XD98M Isuzu CYZ52K LKK REF: CS/CTI21009887/R1vce2