

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009896/APA3Q2**Date:** 15/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507807
Claimant Vehicle No :	SKZ2125T	Insured Vehicle No :	SKD205A
Date of Loss:	17/09/2021	Nature of Claim:	TP
		Claim No:	1524605389SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ2125T	Engine No:	K24W72010916
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Chassis No:	JHMRC1890GC202242
Reg. Date:	08/03/2016 (Man. Year: 2016)	Odometer:	77102 km
Colour:	Grey		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,438.88	4,107.52	4,331.36	51.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,620.00	700.00	30.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,758.88	5,727.52	5,031.36	46.76
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	10,758.88	4,500.00	6,258.88	58.17
+ GST 7.00/7.00% (S\$)	753.12	315.00	438.12	58.17
Nett Amount (S\$)	11,512.00	4,815.00	6,697.00	58.17
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
Nett Liability (S\$)		5,655.00		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment:	21/09/2021		
Date Inspected:	21/09/2021	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Distorted	984.70 FL	*984.70 FL
2	1		*FRT LH DOOR HINGES	Not Necessary	76.20 FL	*- FL
3	1		*FRT LH DOOR CATCH	Not Necessary	38.80 FL	*- FL
4	1		*FRT LH DOOR LOCK	Not Necessary	21.90 FL	*- FL
5	1		*FRT LH DOOR LOWER W/STRIP	Necessary	102.60 FL	*102.60 FL
6	1		*FRT LH DOOR TOP W/STRIP	Not Necessary	102.60 FL	*- FL
7	1		*FRT LH DOOR CHROME	Deformed	110.30 FL	*110.30 FL
8	1		*FRT LH DOOR REGULATOR GEAR W/MOTOR	Damaged	464.00 FL	*464.00 FL
9	1		*FRT LH DOOR STICKER	Necessary	49.70 FL	*49.70 FL
10	1		*FRT LH DOOR OUTER GARNISH	Deformed	346.50 FL	*346.50 FL
11	1		*FRT LH DOOR TRIMBOARD	Cracked	744.10 FL	*744.10 FL
12	1		*FRT LH DOOR OUTR HANDLE	Not Necessary	336.90 FL	*- FL
13	1		*FRT LH DOOR OUTR HANDLE COVER	Not Necessary	43.00 FL	*- FL
14	1		*FRT LH DOOR SPEAKER	Not Necessary	185.50 FL	*- FL
15	1		*FRT LH WING MIRROR	Damaged	1,486.10 FL	*919.00 FL
16	1		*FRT LH WING MIRROR CAMERA	Not Necessary	563.90 FL	*- FL
17	1		*REAR LH DOOR	Distorted	1,067.00 FL	*1,067.00 FL
18	1		*REAR LH DOOR OUTER GARNISH	Deformed	346.50 FL	*346.50 FL
19	1		*REAR LH DOOR LOCK	Not Necessary	983.40 FL	*- FL
20	1		*REAR LH DOOR TRIMBOARD	Not Necessary	392.80 FL	*- FL
21	1		*REAR LH DOOR REGULATOR GEAR W/MOTOR	Not Necessary	429.00 FL	*- FL
22	1		*REAR LH DOOR W/STRIP	Not Necessary	453.90 FL	*- FL
23	1		*REAR LH DOOR LOWER HINGES	Not Necessary	255.10 FL	*- FL
24	1		*LH DOOR PILLAR	Repair	964.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	10,548.60	5,134.40
- List Item Discount on L Items 20.00/20.00% (S\$)	2,109.72	1,026.88
Total Parts (S\$)	8,438.88	4,107.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	TRANSFER 2 DOORS PARTS	New	120.00	120.00
Gross Labour Cost (\$)			2,320.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >