

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SARAH PEK SHAOYUN
BLK 100 TANAH MERAH BESAR ROAD
#09-03
SINGAPORE 498839

Contact : 91726107, 96169955

ESTIMATE

Repair Code : CLM15316

Date in : 22/09/2021

Vehicle Num. : SKV9021J

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11102695/L15B4022698

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER RESONATOR	1	CRK / 180.50	180.50
FRONT AIRCON CONDENSER	1	DEF / 568.10	568.10 568.10
FRONT BONNET	1	DD / 892.30	892.30 892.30
FRONT BONNET HINGES L/R	2	R X 48.50	97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	2	SVC X 23.80	47.60
FRONT BONNET INNER SIDE SEAL L/R	2	NRC / 37.50	75.00
FRONT BONNET INNER TOP SEAL L/R	2	NEL / 23.00	46.00
FRONT BONNET INSULATOR	1	SVC X 122.30	122.30
FRONT BONNET MECHANISM LOCK	1	BS / 95.00	95.00
FRONT BUMPER	1	DEF / 801.70	801.70 801.70
FRONT BUMPER LH FOGLAMP	1	CRK / 327.70	327.70 327.70
FRONT BUMPER LH FOGLAMP BRACKET	1	CRK / 49.00	49.00
FRONT BUMPER LH FOGLAMP GARNISH	1	DEF / 45.00	45.00
FRONT BUMPER LOWER GRILLE	1	DEF / 77.50	77.50
FRONT BUMPER LOWER LID GARNISH	1	CRK / 381.00	381.00 381.00
FRONT BUMPER REINFORCEMENT	1	DD / 321.00	321.00
FRONT BUMPER SIDE RETAINER L/R	1	X LH - CRK 20.60 RH X SVC	20.60 41.20
FRONT FENDER ARCH GARNISH L/R	1	X LH - DEF 220.00 RH X SVC	220.00 440.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SARAH PEK SHAOYUN
BLK 100 TANAH MERAH BESAR ROAD
#09-03
SINGAPORE 498839

Contact : 91726107, 96169955

ESTIMATE

Repair Code : CLM15316

Date in : 22/09/2021

Vehicle Num. : SKV9021J

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng#: RU11102695/L15B4022698

FRONT GRILLE	1	CRK /	351.80	301.20	351.80
FRONT GRILLE 'LOGO' EMBLEM	1	NFC /	23.40		23.40
FRONT GRILLE CENTER BRACKET	1	CRK /	76.00		76.00
FRONT GRILLE CHROME MOULDING L/R	1 2	LH / SCR RH X SVL	55.00	55	110.00
FRONT GRILLE OUTER COVER	1	DEF /	421.00	300	421.00
FRONT GRILLE TOP GARNISH	1	SVL X	85.00		85.00
FRONT HEADLAMP L/R	2	CRK /	1784.50	3,400	1,569.00
FRONT HEADLAMP LOWER BRACKET L/R	2	CRK /	35.00		70.00
FRONT HEADLAMP SIDE BRACKET L/R	1 2	LH - CRK RH X SVL	35.00	35	70.00
FRONT HORN	1	CLT /	110.50	70	110.50
FRONT LH FENDER	1	DEF /	580.00	421.10	580.00
FRONT LH FENDER INNER SHIELD	1	TN /	130.00		130.00
FRONT OUTSIDE TEMPERATURE SENSOR	1	SVL X	80.00		80.00
FRONT OUTSIDE TEMPERATURE SENSOR BRACKET	1	CRK /	25.00		25.00
FRONT SUPPORT PANEL	1	DD /	576.20	526.90	576.20
FRONT WIPER GRILLE GARNISH	1	CRK /	240.00		240.00
RADIATOR (AUTO)	1	DEF /	1376.60	1,242.70	1,376.60
RADIATOR SIDE GUIDE L/R	1 2	LH / DEF RH X SVL	31.60	31.60	63.20

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SARAH PEK SHAOYUN
BLK 100 TANAH MERAH BESAR ROAD
#09-03
SINGAPORE 498839

Contact : 91726107, 96169955

ESTIMATE

Repair Code : CLM15316

Date in : 22/09/2021

Vehicle Num. : SKV9021J

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11102695/L15B4022698

	Subtotal before discount	12,565.60
Percentage discount 20%		2,513.12
	Sub-total 1	10,052.48
BATTERY	1 DEF / 250.00	150 250.00
FRONT BONNET INSULATOR CLIPS - SET	1 NEC / 50.00	50.00
FRONT BUMPER CLIPS - SET	1 NEC / 50.00	50.00
FRONT BUMPER PARKING SENSOR	1 DEF 180 / 250.00	180 250.00
FRONT GRILLE CLIPS - SET	1 NEC / 50.00	30 50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET	1 NEC / 30.00	30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	1 NEC / 50.00	30 50.00
FRONT NUMBER PLATE	1 DEF NFE / 25.00	25.00
FRONT NUMBER PLATE HOLDER	1 DEF 30 / 50.00	30 50.00
FRONT WIPER GRILLE GARNISH CLIPS - SET	1 NEC / 50.00	30 50.00
RADIATOR COOLANT	1 NEC / 60.00	60.00
	Subtotal before discount	665 915.00
Percentage discount 0%		0.00
	Sub-total 2	915.00
	Parts-total	10,967.48

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SARAH PEK SHAOYUN
BLK 100 TANAH MERAH BESAR ROAD
#09-03
SINGAPORE 498839

Contact : 91726107, 96169955

ESTIMATE

Repair Code : CLM15316

Date in : 22/09/2021

Vehicle Num. : SKV9021J

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11102695/L15B4022698

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

100 80 150.00
30 20 80.00
800 1,400.00
800 1,200.00
50 100.00

Labour Total

2,930.00

Parts & Labour Total

13,897.48

1,780

*** This is a computer-generated document which requires no signature.***

page 4

NA2 LKX
24/9/2021 1500
LIS
5 DAYS
AFTER REPAIR PHOTOS

PARTS \$10,589.90
LESS 20% \$8,471.19
NETT \$ 665.00
LABOUR \$1,780.00
\$10,916.92

LESS LIS 20% \$8,733.53
TOTAL \$8,750.00 / 5 REPAIR DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: