



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009903/Uuf3n2  Date: 05/10/2021  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SJN 5522K		<b>Veh. Inspected</b>	SLU 9731L
<b>Policy No.</b>			<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10011796/EE		<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA		<b>Assign Date</b>	22/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA C-HR HYBRID (A)		<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN		<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	ZYG102017039		<b>Colour</b>	BLUE
<b>Odometer</b>	74894 KM		<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER		<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/50 R18	WEST LAKE	6 mm
	<b>L/H Front Tyre</b>	225/50 R18	WEST LAKE	6 mm
	<b>R/H Rear Tyre</b>	225/50 R18	WEST LAKE	6 mm
	<b>L/H Rear Tyre</b>	225/50 R18	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	<b>Accident Date</b>	22/09/2021	<b>Inspection Date</b>	23/09/2021
	<b>Survey held at</b>	YSK AUTO WORKSHOP  1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
	<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>		<b>5 Working Days</b>	