

**Borneo Motors**

T/P claim

**TOYOTA**

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

kindly submit for liability check
 vehicle grounded
 Thanks

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355
	Document No. 0	
	Document Date 22/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3800068291	2NRX543415	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES T/P INS. : T/P VEH. : GBK5772R ACC DATE : 21.09.21 BY :				100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#) (REAR WITH CASING)				80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
4	B	BP-LAB2 RRSET AND REPROGRAMME ECU.				180.00
5	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00
6	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00
7	B	BP-LAB2 REMOVE TAIL-GTAE COMPONENTS TO TRANSFER ONTO NEW DOOR.				360.00
8	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				450.00
9	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.				300.00
10	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR.				360.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355
	Document No. 0	
	Document Date 22/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3800068291	2NRX543415	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER AND TAIL-GATE.				183.18
12	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.				3080.00
13	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				2950.00
14	1	S52159-0U919 COVER, RR BUMPER, L	1.00	319.20		319.20
15	2	S52151-0D010 EXTENSION, RR BUMPER	1.00	191.80		191.80
16	3	S52161-0D070 EXTENSION, RR BUMPER	1.00	130.30		130.30
17	4	S52162-0D040 EXTENSION, RR BUMPER	1.00	130.30		130.30
18	5	SPC507-0D014 24 BACK SENSOR (1G3,GRAY ME)	1.00	174.50		174.50
19	6	S52155-0D110 SUPPORT, RR BUMPER S	1.00	74.10		74.10
20	7	S52156-0D100 SUPPORT, RR BUMPER S	1.00	74.10		74.10
21	8	S52575-0D280 RETAINER, RR BUMPER	1.00	71.10		71.10
22	9	S52576-0D270 RETAINER, RR BUMPER	1.00	71.10		71.10
23	0	S52161-0K040 PIECE,RR BUMPER	4.00	4.10		16.40
24	1	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	438.20		438.20

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
 _____	Please acknowledge receipt of vehicle _____	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355		
			Document No. 0				
			Document Date 22/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
25	2	S64716-0D170 C0 COVER, DECK TRIM, RR	1.00	155.90		155.90	
26	3	S58302-0D010 PANEL SUB-ASSY, LWR	1.00	702.90		702.90	
27	4	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1142.50		1142.50	
28	5	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1041.50		1041.50	
29	6	S64813-0D330 DAM, BACK WINDOW GLA	2.00	12.50		25.00	
30	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00	
31	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
32	9	S76801-0D600 GARNISH SUB-ASSY, BA	1.00	231.80		231.80	
33	0	S75431-0M080 EMBLEM LUGGAGE COMPA	1.00	53.90		53.90	
34	1	S75441-0D070 PLATE, BACK DOOR NAM	1.00	53.70		53.70	
35	2	S75442-0D300 PLATE, BACK DOOR NAM	1.00	35.80		35.80	
36	3	T81270-0D120 LAMP ASSY, LICENSE	2.00	66.30		132.60	
37	4	T89997-30100 ANTENNA, ELECTRICAL	1.00	72.60		72.60	
38	5	T81480-52070 LAMP ASSY, RR FOG,	1.00	236.70		236.70	
39	6	S81580-0D240 LAMP ASSY, RR, RH	1.00	137.40		137.40	
40	7	S81590-0D240 LAMP ASSY, RR, LH	1.00	137.40		137.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 14,869.98
			Please acknowledge receipt of vehicle		Parts	6,266.80	GST 7.00% 1,040.90 Less 0.00 Amount Due 15,910.88
					Labour	8,040.00	
					Sublet	563.18	
					Lubrication/Fluid	0.00	
					Others	0.00	

Customer Copy