

Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

Steve (LKK)
23/9/21, 11.00

WML A.L
12 djs
P/P
M Belong

Stevechen @ IKK auto. com
83228813

ESTIMATE

Account Details		Account No.	Customer Details					
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Tan Mun Chong Desmond (Chen WenCong)					
		Document No. 0	207 Bishan Street 23 #07-399 Singapore 570207					
		Document Date 22/09/2021	Mobile: 92983355					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES T/P INS. : <i>Compac</i> T/P VEH. : GBK5772R ACC DATE : 21.09.21 BY : <i>LKK</i>						50 - 100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#) (REAR WITH CASING)						80.00
3	Z	BP-SLANT SUPPLY SEALANT (NETT)						200.00
4	B	BP-LAB2 RRSET AND REPROGRAMME ECU.						180.00
5	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.						180.00
6	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.						180.00
7	B	BP-LAB2 REMOVE TAIL-GTAE COMPONENTS TO TRANSFER ONTO NEW DOOR.						360.00
8	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.						450.00
9	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.						300.00
10	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR. <i>(photo)</i>						360.00
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Company Copy

Inchcape

Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355		
			Document No.				
			0				
			Document Date				
			22/09/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3800068291		2NRX543415	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR BUMPER AND TAIL-GATE.					183.18
12	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.					3600 2080.00
13	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.					3540 2950.00
14	1	S52159-0U919 COVER, RR BUMPER, L	1.00	319.20			319.20
15	2	S52151-0D010 EXTENSION, RR BUMPER	1.00	191.80			191.80
16	3	S52161-0D070 EXTENSION, RR BUMPER	1.00	130.30			130.30
17	4	S52162-0D040 EXTENSION, RR BUMPER	1.00	130.30			130.30
18	5	SPC507-0D014 24 BACK SENSOR (1G3,GRAY ME)	1.00	174.50			174.50
19	6	S52155-0D110 SUPPORT, RR BUMPER S	1.00	74.10			74.10
20	7	S52156-0D100 SUPPORT, RR BUMPER S	1.00	74.10			74.10
21	8	S52575-0D280 RETAINER, RR BUMPER	1.00	71.10			71.10
22	9	S52576-0D270 RETAINER, RR BUMPER	1.00	71.10			71.10
23	0	S52161-0K040 PIECE,RR BUMPER	4.00	4.10			16.40
24	1	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	438.20			438.20
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy

Inchcape

Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355
	Document No. 0	
	Document Date 22/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	64932	65/DS/SMW5847R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3800068291	2NRX543415	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	2	S64716-0D170 C0 COVER, DECK TRIM, RR ? / CRU	1.00	155.90		155.90 ✓
26	3	S58302-0D010 PANEL SUB-ASSY, LWR (Cm) - DD	1.00	702.90		702.90 ✓
27	4	S67005-0D360 PANEL SUB-ASSY, BACK - DD	1.00	1142.50		1142.50 ✓
28	5	S68105-0D261 GLASS SUB-ASSY, BACK - nec (photo)	1.00	1041.50		1041.50 ✓
29	6	S64813-0D330 DAM, BACK WINDOW GLA - nec	2.00	12.50		25.00 ✓
30	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA - nec	2.00	108.00		216.00 ✓
31	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER - nec	1.00	200.00		200.00 ✓
32	9	S76801-0D600 GARNISH SUB-ASSY, BA (Chase) - nec	1.00	231.80		231.80 ✓
33	0	S75431-0M080 EMBLEM LUGGAGE COMPARTMENT SYMBOL - nec	1.00	53.90		53.90 ✓
34	1	S75441-0D070 PLATE, BACK DOOR NAM - nec	1.00	53.70		53.70 ✓
35	2	S75442-0D300 PLATE, BACK DOOR NAM - nec	1.00	35.80		35.80 ✓
36	3	T81270-0D120 LAMP ASSY, LICENSE - nec	2.00	66.30		132.60 ✓
37	4	T89997-30100 ANTENNA, ELECTRICAL - nec	1.00	72.60		72.60 ✓
38	5	T81480-52070 LAMP ASSY, RR FOG, - nec	1.00	236.70		236.70 ✓
39	6	S81580-0D240 LAMP ASSY, RR, RH (Tail light) - nec	1.00	137.40		137.40 ✓
40	7	S81590-0D240 LAMP ASSY, RR, LH (") - nec	1.00	137.40		137.40 ✓

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	14,869.98	
• To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Please acknowledge receipt of vehicle	Parts	6,266.80	GST 7.00%	1,040.90
		Labour	8,040.00	Less	0.00
		Sublet	563.18		
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	15,910.88

Acknowledged by Repairer

Signature:

Date:

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

**TOYOTA**

Attn: Steve

Supplementary lists

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	Mr Tan Mun Chong Desmond (Chen WenCong) 207 Bishan Street 23 #07-399 Singapore 570207 Mobile: 92983355
	Document No. 0	
	Document Date 02/11/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP170R	MWYNKT S4	27/11/2020	SMW5847R	0	10889	SMW5847R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3800068291	2NRX543415	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	1	S60836-0D010 B1 COVER SUB-ASSY, SLID BR	1.00	467.60		467.60
2	2	S51931-0D180 CARRIER, SPARE WHEEL CRV	1.00	65.20		65.20
3	3	S85292-0D180 CAP, WIPER ARM HEAD CUT	1.00	2.50		2.50
4	4	S52162-0D050 PLATE, RR BUMPER, NO CUT	1.00	21.10		21.10
5	5	S69285-0D080 HANDLE, PULL CRV	1.00	26.40		26.40
6	6	S69350-0D240 LOCK ASSY, BACK DOOR BT	1.00	472.40		472.40
7	7	S81560-0D630 LAMP ASSY, RR COMBIN CUT	1.00	425.30		425.30
8	8	T81481-52560 BRACKET, FOG LAMP BR	1.00	56.50		56.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts 1,537.00	1,537.00
		Labour 0.00	GST 7.00% 107.59
		Sublet 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 1,644.59

Customer Copy